
### **WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT**

Building Address:			Date of Inspection	Number of Pages	
289 Eastbourne terrace, Santa Maria, CA 93455 01/24/2017					
No Problem Exterminators 12793 Concord Ave Chino CA 91710 Phone: (323) 707-6765 Fax: (909) 248-0276					
Ordered by: Maxim Properties, El Segundo Polly Watts 2015 Manhattan Beach Blvd. 100 El Segundo, CA 90278	Property Owner and/or Party of Interest: Maxim Properties, El Segundo Polly Watts 2015 Manhattan Beach Blvd. 100 El Segundo, CA 90278	Report Sent to:  Maxim Properties, El Segundo Polly Watts 2015 Manhattan Beach Blvd. 10 El Segundo, CA 90278		each Blvd. 100	
COMPLETE REPORT ☑ LIMITED REPORT ☐ SUPPLEMENTAL REPORT ☐ REINSPECTION REPORT ☐					
General Description: two-story home composition roofing stucco walls two car garage attached Inspection Tag Posted: Attic					
	Other Tag None	gs Posted:			
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.					
Subterranean Termites  Drywood Termites  Fungus / Dryrot  Other Findings  Further Inspection  If any of the above boxes are checked, it indicates that there were visible problems in accessible areas. Read the report for the details on checked items.					



This Diagram is not to scale

Inspected by: Ruben Lopez State License No. OPR11952 Signature

You are entitled to obtain copies of all reports and completion notices on this property reported to the Structural Pest Control Board during the preceding who years. To obtain copies contact: Structural Pest Control Board, 2005 Evergreen Street, Ste. 1500, Sacramento, California 95815.

#### SECOND PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 289 Eastbourne terrace, Santa Maria, CA 93455

01/24/2017

W14898

Date

Report #

What is a Wood Destroying Pest and Organism Inspection Report?

The following explains the scope and limitations of a structural pest control inspection and a Wood Destroying Pest & Organism Inspection Report.

A Wood Destroying Pest & Organism Inspection Report contains finding as to the presence or absence of wood destroying insects or organisms in visible and accessible areas on the date of inspection and contains our recommendations for correcting any infestations, infections, or conditions found. The contents of the wood destroying pest & organism inspection report are governed by the structural pest control act and its rules and regulations.

Some structures may not comply with building code requirements or may have structural, plumbing, electrical, heating and air conditioning, or other defects that do not pertain to this report. This report does not address any such defects as they are not within the scope of the license of the inspector or the company issuing this report.

The following areas are considered inaccessible for purposes of inspection or are not included in a normal inspection report and therefore are excluded in this report: the interior of hollow walls; spaces between an upstairs floor and the ceiling below or a porch deck and soffit below; stall showers over finished ceilings; such structural segments as areas enclosed by bay windows, buttresses, built in cabinet work, areas under floor covering; any areas requiring the removal of storage, furnishings or appliances; any areas to which there is no access without defacing or removing lumber, masonry or finished workmanship.

Certain areas are recognized by the industry as inaccessible and/or for other reasons not inspected. These include but are not limited to: inaccessible and/or, insulated attics or portions thereof, attics with less than 18" clear crawl space, the interior of hollow walls; spaces between a floor or porch deck and the ceiling below; areas where there is no access without defacing or tearing out lumber, masonry or finished work; make inspection impractical; and areas or timbers around eaves that would require use of an extension ladder.

Certain areas may be inaccessbile for inspection due to construction or storage. We recommend further inspection of areas where inspection was impractical. Re: Structural Pest Control Act, Article 6, section 8516 (b), paragraph 1990 (I). Amended effective March 1, 1974. Stall shower, if any, are water tested in compliance with Section 1991 (12) of the Structural Pest Control Act. The absence or presence of leaks through sub-floor, adjacent floors or walls will be reported. This is a report of the condition of the stall shower at the time of inspection only, and should not be confused as a guarantee. Although we make a visual examination, we do not deface or probe into window or door frames, decorative trim, roof members, etc., in search of wood destroying pests or organisms.

"This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be nessary. Any guarantees must be received from parties performing repairs."

NOTE: We do not inspect or certify plumbing, plumbing fixtures, etc.

NOTE: "The exterior surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contract a roofing contractor who is licensed by the Contractor's State License Board."

"NOTICE: The charge for service that this company subcontracts to another registered company may include the company's charges for arranging and administering such services that are in addition to the direct costs associated with paying the subcontractor. You may accept No Problem Exterminators's bid or you may contract directly with another registered company licensed to perform the work.

If you choose to contract directly with another registered company, No Problem Exterminators will not in any way be responsible for any act or omission in the performance of work that you directly contract with another to perform."

"NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company."

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

"Local treatment is not intended to be an entire structure treatment method. If infestations or wood-destroying pests extend or exist beyond the area(s) of local treatment, they may not be exterminated."

This is a separated report which is defined as Section I/Section II conditions evident on the date of the inspection. Section I contains items where there is visible evidence of active infestation, infection or conditions that have resulted in or from infestation of infection. Section II items are conditions deemed likely to lead to infestation or infection but where no visible evidence of such was found. Further inspection items are defined as recommendations to inspect area(s) which during the original inspection did not allow the inspector access to complete the inspection and cannot be defined as Section I or Section II.

#### THIRD PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 289 Eastbourne terrace, Santa Maria, CA 93455

01/24/2017

W14898

Date

Report #

#### FINDINGS AND RECOMMENDATIONS

Substructure:

slab

Stall Shower:

Tested

Foundations:

Concrete above grade

Porches - Steps:

Concrete

Ventilation:

Adequate Above Grade

Abutments:

None

**Attic Spaces:** 

inspected

7A (Section I)

FINDINGS: Evidence of dry-wood termite infestations at attic as indicated on the diagram.

RECOMMENDATION: Vacate the premises and seal the structure for fumigation with Vikane Gas.

Remove or cover accessible evidence of infestation. Fumigation warranteed for two years. Fumigation awareness notice must be signed prior to fumigation. See fumigation notice for terms and liabilities.

**Garages:** 

Two car attached

8A

(Section I)

FINDINGS: Evidence of subterranean termite infestation at garage as indicated on the diagram. RECOMMENDATION: Pressure "ROD" treat, trench application or low pressure spot spray as necessary. Break accessible sub tubes.

**Decks - Patios:** 

none

Other Interior:

Inspected

Other Exterior:

Inspected

#### FOURTH PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 289 Eastbourne terrace, Santa Maria, CA 93455

01/24/2017

W14898

Date

Report #

In accordance with the laws and regulation of the State of California, we are required to provide you with the following information prior to application of pesticides to your property.

"State law requires that you be given the following information: CAUTION--PESTICIDES ARE TOXIC CHEMICALS. Structural Pest Control Companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Pesticide Regulation and the United States Environmental Protection Agency. Registration is granted when the state finds that, based on existing scientific evidence, there are no appreciable risks if proper use conditions are followed or that the risks are outweighed by the benefits. The degree of risk depends upon the degree of exposure, so exposure should be minimized."

"If within 24 hours following application you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center (800) 876-4766 and your pest control company immediately." "For further information, contact any of the following:

For further information, contact any of the following:

No Problem Exterminators

(323) 707-6765

Poison Control Center

(800) 876-4766

(Health Questions) County Health Dept.
Orange County

(714) 834-7700

Los Angeles County

(213) 250-8055

San Bernardino County

(909) 387-6280

Riverside County

(909) 358-5000

(Application Info.) County Agriculture Commission

Orange County

(714) 447-7100

Los Angeles County

(626) 575-5465

San Bernardino County Riverside County (909) 387-2115

, , , , , , ,

(951) 955-3000

Structural Pest Control Board (Regulatory Info.) (916) 561-8704

2005 Evergreen Street, Ste. 1500 Sacramento, CA 95815

#### TERMITE AND FUNGUS CONTROL CHEMICALS

Vikane (EPA Reg. No. 62719-4)

Active Ingredients: Vikane-sulfuryl floride 99.5%, Chloropicrin .5%

Control of subterranean termites.

Bora-Care (EPA Reg. No. 64405-1)

Active Ingredients: DisodiumOctaborateTetrahydrate 40%

Tengard (EPA Reg. No. 70506-6) Active Ingredients: PERMETHRIN

#### NOTICE TO OWNER

Under the California Mechanics Lien Law any structural pest control company which contracts to do work for you, any contractor, subcontractor, laborer, supplier or other person who helps to improve your property, but is not paid for his or her work or supplies, has a right to enforce a claim against your property. This means that after a court hearing, your property could be sold by a court officer and the proceeds of the sale used to satisfy the indebtedness. This can happen even if you have paid your structural pest control company in full if the subcontractor, laborers or suppliers remain unpaid. To preserve their right to file a claim or lien against your property, certain claimants such as subcontractors or material suppliers are required to provide you with a document entitled "Preliminary Notice." Prime contractors and laborers for wages do not have to provide this notice. A Preliminary Notice is not a lien against your property. Its purpose is to notify you of persons who may have a right to file a lien against your property if they are not paid.

NOTE: If the Home Owner fails to pay billing in full, No Problem Exterminators will have the right to be paid back for all its costs and expenses to the extent not prohibited by applicable law. Those expenses include, for example (but not limited to), reasonable attorney's fees. If for any reason this account is to be turned over to our collection agency, You will be responsible for all cost of collecting.

## FIFTH PAGE OF STANDARD INSPECTION REPORT OF THE PROPERTY LOCATED AT:

Address 289 Eastbourne terrace, Santa Maria, CA 93455

Ω1	/24	120	۱1	7
	<i>''</i>	<i>1 /</i> \ 1	, ,	,

W14898

Date

\_Date\_\_\_

Report #

Item	Approval	Primary Estimate				Section
7A		\$2,350.00				I
8A		\$690.00				I
Comple	te all of the iter	ms quoted above with	Total Estimate	\$3,040.00	Complete only t	he above Items checke
	Estimate.	•	Total Estimate	φ5,040.00	Total \$	
					4	
					•	
nave read	and understan	nd the terms of the Re	port referenced above ar	nd agree to the terr	ns and conditions set forth.	
					it is agreed that payment s	
		_		_	_	
ayment s	shall be made	e as follows: $\square$ $W$	th close of Escrow	S	Deposit	on Completion
Escrow	Number:	Escro	v Company:		Escrow Officer:	
					2001011 01110011	
		_	_		ve's Title:	
wner or a						

Phone: (323) 707-6765 Fax: (909) 248-0276

# Work Authorization

Page 1 of 1

Address: 289 Eastbourne terrace Santa Maria, CA 93455	
Report # W14898 Report Date: 01/24/2017	
The terms of this contract are agreed upon as set forth in the above noted report	
Findings and Recommendations estimated by this Comp	pany:
Item Approval Primary Estimate	Section
7A \$2,350.00	1
8A	I
Complete all of the items quoted above with Primary Estimate \$3,040.00 Primary Estimate.	Complete only the above Items checked.  Total \$
I have read and understand the terms of the Report referenced above and agree to the	terms and conditions set forth.
No Problem Exterminators is hereby authorized to complete the Items selected above follows:	and it is agreed that payment shall be made as
Payment shall be made as follows:   With close of Escrow   \$	Deposit Son Completion
Escrow Number: Escrow Company:	Escrow Officer:
Phone ( ) Fax ( ) Address: _	
Owner or Authorized Representative:   Owner   Representative	s's Title:
Print Name:X	Date
	. <del></del>
Owner or Authorized Representative: U Owner L Representative  Print Name: X	
	<del></del>