
### by ClearCapital

## 1979 Sugar Maple Ln

Perris, CA 92571

**39662** \$375,000 Loan Number • As-Is Value



# **Subject Details**

PROPERTY TYPE	<b>GLA</b>
SFR	2,617 Sq. Ft.
BEDS	<b>BATHS</b>
4	2.0
<b>STYLE</b>	<b>YEAR BUILT</b>
Modern	2010
LOT SIZE	OWNERSHIP
0.28 Acre(s)	Fee Simple
GARAGE TYPE	<b>GARAGE SIZE</b>
Attached Garage	2 Car(s)
<b>HEATING</b>	<b>COOLING</b>
Central	Central
<b>COUNTY</b>	<b>APN</b>
Riverside	320381021

# **Analysis Of Subject**

### **CONDITION RATING**

			_						
1 2	3 4	5 6		1	2	3	4	5	6
The property is w repairs due to no		and feature limited tear.	d				y rating n icable bu		
VIEW				LOCA	TION				
Reside	ntial		_	f F	Reside	ntial			
Beneficial	Neutral	Adverse		Bene	eficial	Neu	tral	Adve	erse

**QUALITY RATING** 

### SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

Subject's site backs to busy street, but with the large setback, there appears to be no negative impact on marketability. The subject has a premium size site that has a positive impact on marketability. It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Informati ... (continued in Appraiser Commentary Summary)

Provided by Appraiser

by ClearCapital

### 1979 Sugar Maple Ln

Perris, CA 92571

# \$375,000

39662

Loan Number

🔶 As-Is Value

# **Sales Comparison**



				MOST COMPAR	RABLE		
	<b>1979 Sugar Maple Ln</b> Perris, CA 92571	1901 El Nido Ave Perris, CA 92571		2 1237 Sunset Ave Perris, CA 92571		3 1173 Viscano Ct Perris, CA 92571	
			CRAILS				
COMPARABLE TYPE		Sale		Sale		Sale	
MILES TO SUBJECT		0.11 miles		0.30 miles		0.29 miles	
DATA/ VERIFICATION SOURCE	MLS	MLS		MLS		MLS	
LIST PRICE	-	-				-	
LIST DATE		09/12/2019		08/26/2019		05/03/2019	
SALE PRICE/PPSF		\$355,000	\$155/Sq. Ft.	\$381,000	\$144/Sq. Ft.	\$439,990	\$164/Sq. Ft.
CONTRACT/ PENDING DATE		10/10/2019		09/04/2019		07/01/2019	
SALE DATE		12/03/2019		10/11/2019		07/31/2019	
DAYS ON MARKET	-	82		46		89	
LOCATION	N; Res	N; Res		N; Res		B; Other: Avelina HOA	-\$20,000
LOT SIZE	0.28 Acre(s)	0.14 Acre(s)	\$5,000	0.18 Acre(s)	\$5,000	0.28 Acre(s)	
VIEW	N; Res	N; Res		N; Res		N; Res	
DESIGN (STYLE)	Modern	Modern		Modern		Contemp	
QUALITY OF CONSTRUCTION	Q4	Q4		Q4		Q4	
ACTUAL AGE	10	15		12		6	
CONDITION	C3	C3		C3		C2	-\$50,000
SALE TYPE		Arms length		Arms length		Arms length	
ROOMS/BEDS/BATHS	10/4/2	8/4/3	-\$3,000	11/5/3	-\$8,000	11/5/3	-\$8,000
GROSS LIVING AREA	2,617 Sq. Ft.	2,288 Sq. Ft.	\$24,000	2,654 Sq. Ft.		2,688 Sq. Ft.	
BASEMENT	None	None		None		None	
HEATING	Central	Central		Central		Central	
COOLING	Central	Central		Central		Central	
GARAGE	2 GA	2 GA		3 GA	-\$5,000	2 GA	
OTHER							
OTHER							
NET ADJUSTMENTS		7.3	\$2% \$26,000	-2.	10% - \$8,000	-17.7	73% - \$78,000
GROSS ADJUSTMENTS		9.0	1% \$32,000	4.	72% \$18,000	17.7	/3% \$78,000
ADJUSTED PRICE			\$381,000		\$373,000		\$361,990

**39662** Loan Number

\$375,000 • As-Is Value



Value Conclusion + Reconciliation

**\$375,000** AS-IS VALUE **0-90 Days** EXPOSURE TIME

**EXTERIOR** INSPECTION PERFORMED BY A 3RD PARTY

### Sales Comparison Analysis

### DESCRIPTION OF COMPARABLE SEARCH CRITERIA

The subject is a single story home that sits on a large lot compared to homes in its immediate area. Most homes are 2-story with smaller GLA and site. Subject is not over-improved, it is just that there have been very limited sales that are exact matches to the subject. Sale 1 was selected for being a single story home similar to the subject, however, much smaller in GLA. Sale 2 was selected for similar GLA and sale 3 was selected to match the subjects site. Sale 3 is a Newly built Pulte MODEL home located in superior community with community pool and spa. All selected comparables were based on the standard guideline and were verified through the Multiple Listing Services (MLS) as Arms-Length-Transactions. All Comps surveyed are from the same demand area and are located within the subject's boundary. All adjustments were made where appropriate. All Comps were given most weight due to their recent sale and are similar to subject in terms of GLA, condition and located in subject area.

### EXPLANATION OF ADJUSTMENTS

The adjustments were based on market reaction and derived by paired sales analysis. The methodology used to determine the specific amount of each adjustment is based on paired sales analysis within subject's market and market reaction to several of the comps in the neighborhood. The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Even if the condition rating is the same as subject, a condition adjustment may still be warranted due to slight upgrades or lack thereof, based on MLS photos and agent commentary. The amount of the condition adjustment was based upon match pairs with remaining comps, if needed. The dissimilarities that have a 0 indicated in the adjustment column means the appraiser has acknowledged the difference; however, the market does not support any adjustment. GLA adjustments were given to sales at \$65 per SF. Most weight is given to comp 2 for lowest net and gross adjustments.

ADDITIONAL COMMENTS (OPTIONAL)

### Reconciliation Summary

The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Weight is given to adjusted sale comparable 2 supported by comps 1 & 3. MLS data is assumed to be more reliable. The comparables presented within this analysis appear to be reliable indicators of value for the subject property. Comparables are located within the subject's market and considered reasonable purchase alternatives for the subject. Suggested value appears reasonable based upon the comparables. The subject's final value estimate is considered reasonable and supported by comp selection.

Subject Comments (Site, Condition, Quality)

Clear Val Plus

by ClearCapital

Subject's site backs to busy street, but with the large setback, there appears to be no negative impact on marketability. The subject has a premium size site that has a positive impact on marketability. It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior photos of the subject did not reveal an item of disrepair. Based upon an exterior-only inspection by the agent and photos, the subject is rated in C3 condition. The agent cited no observable repairs needed and the interior is assumed to be in similar condition as the exterior.

## Neighborhood and Market

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.

## Analysis of Prior Sales & Listings

Subject last sold 06/2017 for \$320,000. The subject was listed 10/2018 but has been withdrawn 02/2019. Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

### Highest and Best Use Additional Comments

The subject is a legally permissible use based on its current zoning. Also, the lot size, shape and land-to-building ratio allow the present structure and indicate a good utilization of the improvements. Based on current market conditions, the existing structure as an SFR is financially feasible and maximal productive use. The highest and best use, as if vacant, would be to construct a Single-Family Residence.

Appraisal Format: Appraisal Report

Client(s): Wedgewood Inc

Property ID: 27749218

Effective: 01/07/2020

Page: 4 of 16

# **Appraiser Commentary Summary**





From Page 1

From Page 7

From Page 5

by ClearCapital

# **Subject Details**

### Appraisal Format: Appraisal Report

Client(s): Wedgewood Inc

# Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?	Event	Date	Price	Data Source
Yes	Withdrawn	Feb 25, 2019	\$356,000	MLS 43853287
LISTING STATUS	<ul> <li>Active</li> </ul>	Feb 21, 2019	\$356,000	MLS 43853287
Listed in Past Year	<ul> <li>Withdrawn</li> </ul>	Jan 28, 2019	\$356,000	MLS 43853287
DATA SOURCE(S) MLS,Public Records	<ul> <li>Active</li> </ul>	Jan 26, 2019	\$356,000	MLS 43853287
	Withdrawn	Dec 17, 2018	\$356,000	MLS TR18253600
<b>EFFECTIVE DATE</b> 01/08/2020	Withdrawn	Dec 3, 2018	\$356,000	MLS 43853287
	<ul> <li>Active</li> </ul>	Dec 1, 2018	\$356,000	MLS TR18253600
	Withdrawn	Nov 26, 2018	\$356,000	MLS TR18253600
	Active	Nov 10, 2018	\$356,000	MLS TR18253600
	<ul> <li>Active</li> </ul>	Oct 21, 2018	\$359,888	MLS TR18253600
	Active	Oct 18, 2018	\$365,000	MLS TR18253600
	Sold	Jun 1, 2017	\$320,000	Public Records
	Withdrawn	May 3, 2017	\$324,900	MLS SR17008887
	Pending	Apr 25, 2017	\$324,900	MLS SR17008887
	<ul> <li>Active</li> </ul>	Apr 19, 2017	\$324,900	MLS 17000540
	Withdrawn	Mar 20, 2017	\$324,900	MLS SR17008887
	Pending	Mar 13, 2017	\$324,900	MLS 17000540
	Withdrawn	Jan 19, 2017	\$324,900	MLS SR17008887
	<ul> <li>Active</li> </ul>	Jan 18, 2017	\$324,900	MLS 17000540
	Withdrawn	Jan 18, 2017	\$3,249,000	MLS SR17008887
	Withdrawn	Jan 16, 2017	\$315,000	MLS SR17008887
	<ul> <li>Active</li> </ul>	Jan 13, 2017	\$315,000	MLS SR17008887

### SALES AND LISTING HISTORY ANALYSIS

Subject last sold 06/2017 for \$320,000. The subject was listed 10/2018 but has been withdrawn 02/2019. Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.



39662

Loan Number



Perris, CA 92571

#### \$375,000 39662 Loan Number

As-Is Value



# Subject Details - Cont.

### Order Information

BORROWER Catamount Properties 2018 LLC

**PROPERTY ID** 27749218

**ORDER TRACKING ID** 20200106\_Citi\_ClearVal 39662

**ORDER ID** 

LOAN NUMBER

6479486

**TRACKING ID 1** 20200106\_Citi\_ClearVal

### Legal

**ZONING DESC. OWNER** CORRALES, DAVID NICK Residential **ZONING COMPLIANCE ZONING CLASS** R1 Legal LEGAL DESC. .28 ACRES M/L IN LOT 36 MB 410/022 TR 31660

Highest and Best Use		Economic		
IS HIGHEST AND BEST USE THE PRESENT USE Yes		<b>R.E. TAXES</b> \$6,321	<b>HOA FEES</b> N/A	<b>PROJECT TYPE</b> N/A
PHYSICALLY POSSIBLE?	FINANCIALLY FEASIBLE?	<b>FEMA FLOOD ZO</b> 06065C1440H	NE	
LEGALLY PERMISSABLE?	MOST PRODUCTIVE USE?	FEMA SPECIAL F No	LOOD ZONE AREA	

Effective: 01/07/2020

#### \$375,000 39662 Loan Number

As-Is Value


Provided by

Appraiser

# **Neighborhood + Comparables**

**Clear** Val Plus

by ClearCapital



### YEAR BUILT






Avg Days Until Sale 15

### **NEIGHBORHOOD & MARKET COMMENTS**

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.



SITE SIZE



by ClearCapital

As-Is Value

# **Subject Photos**



Front



Address Verification



Side



Street

Effective: 01/07/2020

by ClearCapital

### 1979 Sugar Maple Ln

Perris, CA 92571

# **39662** \$3

**\$375,000** • As-Is Value



**Comparable Photos** 

1901 El Nido Ave Perris, CA 92571



Front





Front

3 1173 Viscano Ct Perris, CA 92571



Front Appraisal Format: Appraisal Report

39662

Loan Number



# Scope of Work

#### **REPORT FORMAT:**

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

#### PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

#### SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Julie Prigmore, a licensed real estate agent having completed the above referenced Property Inspection.

#### AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

#### THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

#### **INTENDED USE:**

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

#### **INTENDED USER:**

The intended user of this appraisal report is the lender/client.

#### DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

#### (Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS none

39662

Loan Number

# Assumptions, Conditions, Certifications, & Signature

Provided by Appraiser

**EXTRAORDINARY ASSUMPTIONS** 

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS none

39662

Loan Number

Assumptions, Conditions, Certifications, & Signature (Cont.)

I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

Clear Val Plus

by ClearCapital

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Julie Prigmore and did not make a personal inspection of the property that is the subject of this report.
- 10.1 personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is gualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS none

SIGNATURE	<b>NAME</b>	<b>EFFECTIVE DATE</b> 01/07/2020	<b>DATE OF REPORT</b>
Keish-Broog-	Keisha Brookins		01/07/2020
LICENSE #	<b>STATE</b>	<b>EXPIRATION</b>	<b>COMPANY</b>
AR033309	CA	03/09/2020	Sonlite Appraisal Service

Property ID: 27749218

Effective: 01/07/2020





1979 Sugar Maple Ln

Perris, CA 92571



39662

Loan Number

Provided by Onsite Inspector

# **Property Condition Inspection**



PROPERTY TYPE	CURRENT USE	PROJECTED USE
SFR	SFR	SFR
OCCUPANCY	GATED COMMUNITY	ATTACHED TYPE
Unknown	No	Detached
PARKING TYPE Attached Garage; 2 spaces	STORIES 1	UNITS 1

### Condition & Marketability

CONDITION	~	Good	The subject property is a one story home with a stucco exterior with wood trim, tile roof and metal roll-up garage door. The subject appears to be maintained and conforms to the neighborhood.
SIGNIFICANT REPAIRS NEEDED	~	No	No repairs noted at inspection.
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	-
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	~	Yes	-
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	-
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	~	No	-
SUBJECT NEAR POWERLINES	~	No	-
SUBJECT NEAR RAILROAD	~	No	-
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	-

Appraisal Format: Appraisal Report

Effective: 01/07/2020



# **POSITIVE EXTERNALITIES** No $\checkmark$

Condition & Marketability - cont.			
SUBJECT IN FLIGHT PATH OF AIRPORT	~	No	-
ROAD QUALITY	~	Good	-
NEGATIVE EXTERNALITIES	~	No	-

1979 Sugar Maple Ln

Perris, CA 92571



As-Is Value

Provided by Onsite Inspector

# **Repairs Needed**

Exterior Repair	rs	
ITEM	COMMENTS	COST
Exterior Paint		\$0
Siding/Trim Repair	-	\$0
Exterior Doors	-	\$0
Windows		\$0
Garage /Garage Door		\$0
Roof/Gutters	-	\$0
Foundation	-	\$0
Fencing	-	\$0
Landscape	-	\$0
Pool /Spa	-	\$0
Deck/Patio	-	\$0
Driveway	-	\$0
Other	-	\$O
	TOTAL EXTERIOR REPA	IRS <b>\$0</b>

# Clear Val Plus by ClearCapital

\$375,000

As-Is Value

# Agent / Broker

**ELECTRONIC SIGNATURE** /Julie Prigmore/ LICENSE # 01278020

**NAME** Julie Prigmore **COMPANY** Century 21 Award **INSPECTION DATE** 01/07/2020