
by ClearCapital

Clear Val Plus





Subject Details

PROPERTY TYPE GLA

SFR 1,216 Sq. Ft.

BEDS BATHS 1.0

STYLE YEAR BUILT Conventional 1948

LOT SIZE OWNERSHIP 0.14 Acre(s) Fee Simple

GARAGE TYPE GARAGE SIZE 0 Car(s) None

HEATING COOLING Unknown Unknown


COUNTY APN

Los Angeles 8166017015

Analysis Of Subject




CONDITION RATING




The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

QUALITY RATING




Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW



LOCATION



SUBJECT COMMENTS (SITE, CONDITION, QUALITY)


The subject garage appears to have been converted to living space. The subject has a driveway with no covering. It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior phot ... (continued in Appraiser Commentary Summary)





Sales Comparison

Appraiser



Effective: 01/15/2020

8920 Bright Ave

Whittier, CA 90602 Loan Number \$510,000

As-Is Value

Value Conclusion + Reconciliation

Provided by Appraiser

\$510,000 AS-IS VALUE

0-90 Days **EXPOSURE TIME** **EXTERIOR** INSPECTION PERFORMED BY A 3RD PARTY

39732

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

A thorough search of the market was conducted to find the most recent and similar sales to match the subject property. Due to the subject's uniqueness and location, there were no exact model matches available. Dated sales over 6 months were necessary to consider for full compatibility. Every effort was made to bracket the subjects bathroom count, but none were available. The sales selected were the best available. The heating and cooling for the subject is unknown, therefore, no adjustments are made for heating cooling differences. All selected comparables were based on the standard guideline and were verified through the Multiple Listing Services (MLS) as Arms-Length-Transactions. All Comps surveyed are from the same demand area and are located within the subject's boundary. All adjustments were made where appropriate. All Comps were given most weight due to their recent sale and are similar to subject in terms of GLA, condition and located in subject area.

EXPLANATION OF ADJUSTMENTS

The adjustments were based on market reaction and derived by paired sales analysis. The methodology used to determine the specific amount of each adjustment is based on paired sales analysis within subject's market and market reaction to several of the comps in the neighborhood. The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Even if the condition rating is the same as subject, a condition adjustment may still be warranted due to slight upgrades or lack thereof, based on MLS photos and agent commentary. The amount of the condition adjustment was based upon match pairs with remaining comps, if needed. Comp 1 & 2 have some renovation and adjusted for condition and storage unit. The dissimilarities that have a 0 indicated in the adjustment column means the appraiser has acknowledged the difference; however, the market does not support any adjustment. Most weight is given to comp 1 for lowest net and gross adjustments.

ADDITIONAL COMMENTS (OPTIONAL)

The contract/pending date have been provided when available. The unknown box may be checked to indicate that this information could not found or was not available due to some privacy issues. The subject and comparable information were populated from ClearProp and cross referenced with online data sources. There were no discrepancies noted from the data found.

Reconciliation Summary

The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Weight is given to adjusted sale comparable 1 supported by comps 2 & 3. MLS data is assumed to be more reliable. The comparables presented within this analysis appear to be reliable indicators of value for the subject property. Comparables are located within the subject's market and considered reasonable purchase alternatives for the subject. Suggested value appears reasonable based upon the comparables. The subject's final value estimate is considered reasonable and supported by comp selection.

8920 Bright Ave

Whittier, CA 90602

39732 Loan Number \$510,000 • As-Is Value

Appraiser Commentary Summary



Provided by Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

The subject garage appears to have been converted to living space. The subject has a driveway with no covering. It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior photos of the subject did not reveal an item of disrepair. Based upon an exterior-only inspection by the agent and photos, the subject is rated in C4 condition. The agent cited no observable repairs needed and the interior is assumed to be in similar condition as the exterior.

Neighborhood and Market

From Page 6

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.

Analysis of Prior Sales & Listings

From Page 5

Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

Highest and Best Use Additional Comments

The subject is a legally permissible use based on its current zoning. Also, the lot size, shape and land-to-building ratio allow the present structure and indicate a good utilization of the improvements. Based on current market conditions, the existing structure as an SFR is financially feasible and maximal productive use. The highest and best use, as if vacant, would be to construct a Single-Family Residence.

Subject Details





Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS? Event Date Price Data Source

No

LISTING STATUS

Not Listed in Past Year

DATA SOURCE(S)

MLS

EFFECTIVE DATE

01/15/2020

SALES AND LISTING HISTORY ANALYSIS

Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

Order Information

BORROWER LOAN NUMBER

Catamount Properties 2018

LLC

PROPERTY ID

ORDER ID

39732

27793725 6490141

ORDER TRACKING ID TRACKING ID 1

20200114_Citi_ClearVal 20200114_Citi_ClearVal

Legal

OWNER ZONING DESC.

SANDERS, JACOBUS & EDITH Residential

1

ZONING CLASS ZONING COMPLIANCE

WHR1YY Legal

LEGAL DESC.

TRACT # 15431 LOT 88

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE? FINANCIALLY FEASIBLE?

MOST PRODUCTIVE USE?

LEGALLY PERMISSABLE?

Economic

R.E. TAXES HOA FEES PROJECT TYPE

\$812 N/A N/A

FEMA FLOOD ZONE

06037C1835F

FEMA SPECIAL FLOOD ZONE AREA

No

Neighborhood + Comparables




















NEIGHBORHOOD & MARKET COMMENTS

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.



Subject Photos



Front



Address Verification



Side



Side



Street



Street

Comparable Photos



Provided by Appraiser





Front

2 13148 Shreve Rd Whittier, CA 90602



Front





Front

8920 Bright Ave Whittier, CA 90602

\$510,000 As-Is Value

Loan Number

39732



by ClearCapital





This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Lawrence D. Zavala, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Effective: 01/15/2020

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

8920 Bright Ave

Whittier, CA 90602 Loan Number

39732

\$510,000

• As-Is Value

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Lawrence D. Zavala and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

none

SIGNATURE NAME EFFECTIVE DATE DATE OF REPORT

Keisha Brookins 01/15/2020 01/15/2020

LICENSE # STATE EXPIRATION COMPANY

AR033309 CA 03/09/2020 Sonlite Appraisal Service

Effective: 01/15/2020

Whittier, CA 90602

39732 Loan Number \$510,000 • As-Is Value



Property Condition Inspection





PROPERTY TYPE CURRENT USE PROJECTED USE
SFR SFR SFR

OCCUPANCY GATED COMMUNITY ATTACHED TYPE
Occupied No Detached

PARKING TYPESTORIESUNITSDriveway; 2 spaces11

EXTERIOR REPAIRS INTERIOR REPAIRS TOTAL REPAIRS

\$0 N/A \$0

Condition & Marketability			
CONDITION	~	Good	Subject is a Ranch SFR. Subject is in good condition with a stucco exterior and a composition shingle roof. Subject has no observable damage or required repairs.
SIGNIFICANT REPAIRS NEEDED	~	No	Subject has no observable damage or required repairs.
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	There are no current zoning violations or potential zoning changes.
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	~	Yes	The subject conforms to the surrounding neighborhood, which consists of SFR's of the same style, quality and size as the subject.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	The surrounding neighborhood consists of SFR's that are in similar condition as the subject.
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	~	No	There are no boarded or vacant properties near the subject.
SUBJECT NEAR POWERLINES	~	No	There are no powerlines near the subject.
SUBJECT NEAR RAILROAD	A	Yes	There are railroad lines 1/4 mile to the subject's South.
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	The subject is not located near any commercial properties.

Whittier, CA 90602 Loan Number

\$510,000• As-Is Value

39732

Property Condition Inspection - Cont.



Condition & Marketability - cont.		
SUBJECT IN FLIGHT PATH OF AIRPORT	✓ No	The subject is not located in the flight path of an airport.
ROAD QUALITY	✓ Good	The road quality in the subject's neighborhood is in good condition.
NEGATIVE EXTERNALITIES	▲ Yes	There are Railroad tracks 1/4 mile South of the subject.
POSITIVE EXTERNALITIES	✓ Yes	The subject is located 1/2 mile Northwest of local shopping and 2.5 miles Southwest of the 605 freeway.

Repairs Needed

TENA	COMMENTS	20	CT
ITEM	COMMENTS	Co	ST
Exterior Paint	Appears Good	\$0	
Siding/Trim Repair	Appears Good	\$0	
Exterior Doors	Appears Good	\$0	
Windows	Appears Good	\$0	
Garage /Garage Door	N/A	\$0	
Roof/Gutters	Appears Good	\$0	
Foundation	Unknown	\$0	
Fencing	Appears Good	\$0	
Landscape	Appears Good	\$0	
Pool /Spa	N/A	\$0	
Deck/Patio	N/A	\$0	
Driveway	Appears Good	\$0	
Other	N/A	\$0	
		TOTAL EXTERIOR REPAIRS	\$0

39732 Loan Number **\$510,000**• As-Is Value

Agent / Broker

ELECTRONIC SIGNATURE

/Lawrence D. Zavala/

LICENSE # 01462661

NAME

Lawrence D. Zavala

COMPANY

BRC Realty Group

INSPECTION DATE

01/15/2020