


INSPECTION PHOTO Tue, February 04, 2020 03:19PM




Subject Details

PROPERTY TYPE	GLA
SFR	1,769 Sq. Ft.
BEDS	BATHS
4	2.0
STYLE	YEAR BUILT
Conventional	1929
LOT SIZE	OWNERSHIP
0.12 Acre(s)	Fee Simple
GARAGE TYPE	GARAGE SIZE
Detached Garage	2 Car(s)
HEATING	COOLING
Central	Unknown
COUNTY	APN
Los Angeles	6201015021

Analysis Of Subject


Provided by Appraiser

CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.


QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.


VIEW

Residential



LOCATION

Residential




SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The subject appears to be a detached SFR with a Q4 quality rating and C4 condition rating based upon available online data and third party inspection report. I No negative external influences noted by aerial imagery

Sales Comparison

Provided by
Appraiser



	MOST COMPARABLE			
	1 2507 Live Oak St Huntington Park, CA 90255	2 2527 Flower St Huntington Park, CA 90255	3 2654 Flower St Huntington Park, CA 90255	4 2560 Flower St Huntington Park, CA 90255
COMPARABLE TYPE	--	Sale	Sale	Sale
MILES TO SUBJECT	--	0.08 miles	0.27 miles	0.15 miles
DATA/ VERIFICATION SOURCE	Public Records	MLS; Tax Records	Public Records; Tax Records	MLS; Tax Records
LIST PRICE	--	--	--	--
LIST DATE	--	08/21/2019	10/15/2019	03/19/2019
SALE PRICE/PPSF	--	\$515,000 \$341/Sq. Ft.	\$460,000 \$280/Sq. Ft.	\$460,000 \$239/Sq. Ft.
CONTRACT/ PENDING DATE	--	09/06/2019	Unknown	Unknown
SALE DATE	--	11/01/2019	10/15/2019	07/18/2019
DAYS ON MARKET	--	72	0	121
LOCATION	N; Res	N; Res	N; Res	A; Comm \$25,000
LOT SIZE	0.12 Acre(s)	0.14 Acre(s)	0.13 Acre(s)	0.14 Acre(s)
VIEW	N; Res	N; Res	N; Res	N; Res
DESIGN (STYLE)	Conventional	Conventional	Conventional	Conventional
QUALITY OF CONSTRUCTION	Q4	Q4	Q4	Q4
ACTUAL AGE	91	92	99	98
CONDITION	C4	C3 -\$50,000	C4	C4
SALE TYPE		Arms length	Arms length	Arms length
ROOMS/BEDS/BATHS	7/4/2	5/3/1.1 \$5,000	7/4/2	6/3/2
GROSS LIVING AREA	1,769 Sq. Ft.	1,511 Sq. Ft. \$15,480	1,640 Sq. Ft. \$7,740	1,924 Sq. Ft. -\$9,300
BASEMENT	None	None	None	None
HEATING	Central	Forced Air	Forced Air	Forced Air
COOLING	Unknown	Unknown	Unknown	None
GARAGE	2 GD	2 GD	1 GA \$10,000	2 GD
OTHER	--	--	--	--
OTHER	--	--	--	--
NET ADJUSTMENTS		-5.73% -\$29,520	3.86% \$17,740	3.41% \$15,700
GROSS ADJUSTMENTS		13.69% \$70,480	3.86% \$17,740	7.46% \$34,300
ADJUSTED PRICE		\$485,480	\$477,740	\$475,700

Value Conclusion + Reconciliation

 Provided by Appraiser

\$480,000
AS-IS VALUE

1-90 Days
EXPOSURE TIME

EXTERIOR
INSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

A one mile radius search of detached homes was used.

EXPLANATION OF ADJUSTMENTS

Comps selected were proximately located to the subject and would be adjusted for differences in GLA, room count and condition. #3 adjusts upward for inferior location (siding to commercial use).

ADDITIONAL COMMENTS (OPTIONAL)

comp 3 had sale date over 6 months from effective date but was included to bracket GLA.

Reconciliation Summary

Most weight given to comp 2 as it required fewest overall adjustments.

Appraiser Commentary Summary

 Provided by
Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

The subject appears to be a detached SFR with a Q4 quality rating and C4 condition rating based upon available online data and third party inspection report. I No negative external influences noted by aerial imagery

Neighborhood and Market

From Page 6

As of the effective date of report, the data available indicated values were stable, demand and supply were in balance and marketing times were under 3 months; the most recent HDI information provided to reviewer confirms these mostly stable value trends. REO activity is low and area is not REO driven.

Analysis of Prior Sales & Listings

From Page 5

The subject has not transferred in the past 3 years. Per Zillow, there was a listing as of 7/13/19, reported as removed as of 1/31/20. Per Zillow: This property is being offered at Public Auction on 01-30-2020.

Highest and Best Use Additional Comments

The subject use as a detached SFR was deemed highest and best use.

Subject Details

 Provided by Appraiser

Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?

	Event	Date	Price	Data Source
No	● Withdrawn	Jan 30, 2020	\$516,094	Other

LISTING STATUS

Not Listed in Past Year

DATA SOURCE(S)

Public Records

EFFECTIVE DATE

02/05/2020

SALES AND LISTING HISTORY ANALYSIS

The subject has not transferred in the past 3 years. Per Zillow, there was a listing as of 7/13/19, reported as removed as of 1/31/20. Per Zillow: This property is being offered at Public Auction on 01-30-2020.

Order Information

BORROWER	LOAN NUMBER
Catamount Properties 2018 LLC	40032
PROPERTY ID	ORDER ID
27914091	6515215
ORDER TRACKING ID	TRACKING ID 1
Citi_ClearVal_02.03.20	Citi_ClearVal_02.03.20

Legal

OWNER	ZONING DESC.
AGUIANO,CAROLINA	Residential
ZONING CLASS	ZONING COMPLIANCE
LCR305	Legal
LEGAL DESC.	
TRACT # 2263 LOT 92	

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE
Yes


PHYSICALLY POSSIBLE?	FINANCIALLY FEASIBLE?
✓	✓
LEGALLY PERMISSABLE?	MOST PRODUCTIVE USE?
✓	✓

Economic

R.E. TAXES	HOA FEES	PROJECT TYPE
\$4,158	N/A	N/A
FEMA FLOOD ZONE		
06037C1805F		
FEMA SPECIAL FLOOD ZONE AREA		
No		

Neighborhood + Comparables

Provided by Appraiser



Sales in Last 12M

16


Months Supply

1.7

Avg Days Until Sale





10

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

As of the effective date of report, the data available indicated values were stable, demand and supply were in balance and marketing times were under 3 months; the most recent HDI information provided to reviewer confirms these mostly stable value trends. REO activity is low and area is not REO driven.



Subject Photos




Front




Address Verification



Side



Side



Street



Street

Comparable Photos

Provided by
Appraiser

1 2527 Flower St
Huntington Park, CA 90255




Front

2 2654 Flower St
Huntington Park, CA 90255



Front

3 2560 Flower St
Huntington Park, CA 90255



Front

Scope of Work



Provided by
Appraiser

REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and the opinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Francisco Ursulo, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
2. consulted and considered supplemental market data from readily available data sources;
3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

1. buyer and seller are typically motivated;
2. both parties are well informed or well advised, and acting in what they consider their own best interest;
3. a reasonable time is allowed for exposure in the open market;
4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

1. I have, at a minimum, developed and reported this appraisal in accordance with the scope of work requirements stated in this appraisal report. ♦

Assumptions, Conditions, Certifications, & Signature

 Provided by
Appraiser

EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Francisco Ursulo and did not make a personal inspection of the property that is the subject of this report.
10. I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

SIGNATURE

NAME

Kevin Felgenhauer

EFFECTIVE DATE

02/04/2020

DATE OF REPORT

02/04/2020

LICENSE #

AR034060

STATE

CA

EXPIRATION

05/18/2020

COMPANY

At Home Appraisals

Comments - Continued

 Provided by
Appraiser


SCOPE OF WORK COMMENTS

1. I have, at a minimum, developed and reported this appraisal in accordance with the scope of work requirements stated in this appraisal report. 

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

3. Based on reviewing the exterior photos and aerial imagery (when available), the extraordinary assumption has been made that there are no adverse site conditions or external factors (easements, encroachments, environmental conditions, land uses, etc) for the subject property other than those noted in review and the boundary lines of the property are as stated in public records. The appraiser has not reviewed a current survey of the land or the title.

LIMITING CONDITIONS COMMENTS

2. I relied on the additional data sources for subject property characteristics and the physical inspection information and photos performed by a local real estate professional (as stated in section 9 of the reviewer certification) and did not make a personal inspection of the property that is the subject of this report. I relied on the provided exterior photos and aerial imagery (when available) to report the condition of the improvements in factual, specific terms, and I used the provided exterior photos to identify and report the physical deficiencies that could affect the liveability, soundness, or structural integrity of the property. 

Property Condition Inspection

Provided by
Onsite Inspector



PROPERTY TYPE	CURRENT USE	PROJECTED USE
SFR	SFR	SFR
OCCUPANCY	GATED COMMUNITY	ATTACHED TYPE
Occupied	No	Detached
PARKING TYPE	STORIES	UNITS
Detached Garage; 2 spaces	1	1
EXTERIOR REPAIRS	INTERIOR REPAIRS	TOTAL REPAIRS
\$0	N/A	\$0

Condition & Marketability

CONDITION	✓ Good	Property appeared to be in good condition from the exterior.
SIGNIFICANT REPAIRS NEEDED	✓ No	No repairs needed or damages to report at time of inspection.
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	✓ No	No current or potential zoning violations noted at time of inspection.
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	✓ Yes	Subject conforms to neighborhood and is in similar condition to surrounding properties.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	✓ Good	The average condition for the neighboring properties is noted as "Good"
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	✓ No	No boarded or vacant properties were noted at time of inspection.
SUBJECT NEAR POWERLINES	✓ No	No near powerlines were noted or observed.
SUBJECT NEAR RAILROAD	✓ No	Subject is not near any railroad tracks.
SUBJECT NEAR COMMERCIAL PROPERTY	✓ No	There is no nearby commercial properties that would affect subject's marketability.

Property Condition Inspection - Cont.

 Provided by
Onsite Inspector

Condition & Marketability - cont.

SUBJECT IN FLIGHT PATH OF AIRPORT	✓ No	Subject is not near an airport or airport flight path.
ROAD QUALITY	✓ Good	Subject's nearby roads are in good condition and consistent with nearby streets located in and around this neighborhood.
NEGATIVE EXTERNALITIES	✓ No	There are no negative externalities that affect subject property.
POSITIVE EXTERNALITIES	✓ No	There are no positive externalities that affect subject property.

Repairs Needed

Exterior Repairs

ITEM	COMMENTS	COST
Exterior Paint	-	\$0
Siding/Trim Repair	-	\$0
Exterior Doors	-	\$0
Windows	-	\$0
Garage /Garage Door	-	\$0
Roof/Gutters	-	\$0
Foundation	-	\$0
Fencing	-	\$0
Landscape	-	\$0
Pool /Spa	-	\$0
Deck/Patio	-	\$0
Driveway	-	\$0
Other	-	\$0
TOTAL EXTERIOR REPAIRS		\$0

Agent / Broker

ELECTRONIC SIGNATURE	LICENSE #	NAME	COMPANY	INSPECTION DATE
/Francisco Ursulo/	01946059	Francisco Ursulo	SYBIL STEVENSON	02/04/2020