
Clear Val Plus





Subject Details

PROPERTY TYPE GLA

SFR 1,348 Sq. Ft.

BEDS BATHS 2.0

STYLE YEAR BUILT Conventional 1940

LOT SIZE OWNERSHIP 0.15 Acre(s) Fee Simple

GARAGE TYPE GARAGE SIZE Detached Garage 2 Car(s)

HEATING COOLING Forced Air None

COUNTY **APN**

Los Angeles 7017027005

Analysis Of Subject



CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

QUALITY RATING

Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW



Beneficial Neutral Adverse

LOCATION



SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The overall condition, quality of the improvements was rated average condition. The long-lived components; windows, roofing system were observed in working order at the time of inspection. Site reportedly typical for the general market area.



Sales Comparison



		MOST COMPAR	ABLE				
	10308 Park St Bellflower, CA 90706	10103 Beach St Bellflower, CA 90706	6	2 16222 Oregon Ave Bellflower, CA 90706		3 10225 Midway St Bellflower, CA 90706	
	G0/17 2000 12 20 PA		CRAILS				CRMIS
COMPARABLE TYPE		Sale		Sale		Sale	
MILES TO SUBJECT		0.24 miles		0.60 miles		0.42 miles	
DATA/ VERIFICATION SOURCE	Public Records	MLS		MLS		MLS	
LIST PRICE							
LIST DATE		08/13/2019		08/30/2019		07/23/2019	
SALE PRICE/PPSF		\$627,000	\$476/Sq. Ft.	\$533,000	\$361/Sq. Ft.	\$635,000	\$434/Sq. Ft.
CONTRACT/ PENDING DATE		11/23/2019		10/08/2019		08/13/2019	
SALE DATE	-	12/20/2019		12/09/2019		09/09/2019	
DAYS ON MARKET		129		101		48	
LOCATION	N; Other: Fwy	N; Other: Fwy		N; Other: Fwy		N; Other: Fwy	
LOT SIZE	0.15 Acre(s)	0.19 Acre(s)	-\$17,000	0.15 Acre(s)		0.20 Acre(s)	-\$22,000
VIEW	N; Res	N; Res		N; Res		N; Res	
DESIGN (STYLE)	Conventional	Conventional		Conventional		Conventional	
QUALITY OF CONSTRUCTION	Q4	Q4		Q4		Q4	
ACTUAL AGE	80	61		60		80	
CONDITION	C4	C4		C4		C3	-\$15,000
SALE TYPE		Arms length		Arms length		Arms length	
ROOMS/BEDS/BATHS	6/2/2	7/3/2	-\$15,000	6/2/1	\$8,000	8/4/2	-\$30,000
GROSS LIVING AREA	1,348 Sq. Ft.	1,317 Sq. Ft.		1,477 Sq. Ft.	-\$7,095	1,462 Sq. Ft.	-\$7,975
BASEMENT	None	None		None		None	
HEATING	Forced Air	Forced Air		Forced Air		Forced Air	-\$5,000
COOLING	None	Central	-\$5,000	None		Central	
GARAGE	2 GD	2 GD		2 GA		2 GD	
OTHER	No Pool	No Pool		No Pool		Pool	-\$15,000
OTHER							
NET ADJUSTMENTS		-5.9	90% - \$37,000	0.	17% \$905	-14.	96% - \$94,975
GROSS ADJUSTMENTS		5.9	90% \$37,000	2.8	33% \$15,095	14.	96% \$94,975
ADJUSTED PRICE			\$590,000		\$533,905		\$540,025

Effective: 02/12/2020

10308 Park St Bellflower, CA 90706 40131 Loan Number \$590,000

• As-Is Value

Value Conclusion + Reconciliation

Provided by Appraiser

\$590,000AS-IS VALUE

15-130 DaysEXPOSURE TIME

EXTERIORINSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

The appraiser's search revealed that all comparables utilized in this report are the best available data from subject's general neighborhood and market area at time of inspection. All comps were reported as standard sales. Comparable sales bracket the subject's square footage.

EXPLANATION OF ADJUSTMENTS

Through paired sales analysis the market indicated homes with 2 bathrooms command higher prices/values versus homes with 1 bathroom thus adjustments warranted in the sales grid. Through paired sales analysis the market indicated homes with 3 bedrooms command higher prices/values versus homes with 2 bedroom thus adjustments warranted in the sales grid. All adjustments made for GLA, bath count, bed count to comparables were derived through paired sales analysis of the immediate market neighborhood and applied in the sales comparison approach to said closed sale comparables. Opinion of market value was derived from unadjusted and adjusted sale price ranges of comparable sales within the subject's immediate market area.

ADDITIONAL COMMENTS (OPTIONAL)

Reconciliation Summary

Most weight to value was placed on comparable sale 1 when considering immediate market area and most recent date of sale. After all other adjustments were made an as-is opinion of value is \$590,000.

10308 Park St Bellflower, CA 90706 40131 Loan Number \$590,000

• As-Is Value

Appraiser Commentary Summary



Subject Comments (Site, Condition, Quality)

From Page 1

The overall condition, quality of the improvements was rated average condition. The long-lived components; windows, roofing system were observed in working order at the time of inspection. Site reportedly typical for the general market area.

Neighborhood and Market

From Page 6

The MLS and Corelogic reported stability of prices and values for the general area of a rate increase of .1% for all quarters of 2019, into 2020. The average marketing time range was reported at 15 to 130 days, and reasonable marketing exposure time was 55 days. Conventional/FHA financing loans are typically sought in general neighborhood market area. Source: MLS/Corelogic

Analysis of Prior Sales & Listings

From Page 5

No prior sale transfer for the subject in the past 36 months as the tax rolls. No reported prior sale transfer for comparable sales in the past 12 months.

Highest and Best Use Additional Comments

The subject property does adhere highest and best use guidelines and standards.



Subject Details



Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS? **Event** Date **Price Data Source**

No

LISTING STATUS

Not Listed in Past Year

DATA SOURCE(S)

Public Records, Tax Records

EFFECTIVE DATE

02/12/2020

SALES AND LISTING HISTORY ANALYSIS

No prior sale transfer for the subject in the past 36 months as the tax rolls. No reported prior sale transfer for comparable sales in the past 12 months.

Order Information

BORROWER LOAN NUMBER

Catamount Properties 2018

LLC

PROPERTY ID

40131 ORDER ID

28011724 6591076

ORDER TRACKING ID TRACKING ID 1

Citi_ClearVal_02.11.20 Citi_ClearVal_02.11.20 Legal

OWNER ZONING DESC.

OKOLI, GODWIN ETAL Residential

ZONING CLASS ZONING COMPLIANCE

R1 Legal

LEGAL DESC.

TRACT # 4688 LOT 59

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE? FINANCIALLY FEASIBLE?

LEGALLY PERMISSABLE? MOST PRODUCTIVE USE?

Economic

PROJECT TYPE R.E. TAXES HOA FEES

\$5,331 N/A N/A

FEMA FLOOD ZONE

06037C1840F

FEMA SPECIAL FLOOD ZONE AREA

No

Clear Val Plus

Neighborhood + Comparables





Sales in Last 12M 23

Months Supply 1.3


Avg Days Until Sale 55

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

The MLS and Corelogic reported stability of prices and values for the general area of a rate increase of .1% for all quarters of 2019, into 2020. The average marketing time range was reported at 15 to 130 days, and reasonable marketing exposure time was 55 days. Conventional/FHA financing loans are typically sought in general neighborhood market area. Source: MLS/Corelogic



Clear Val Plus

Subject Photos



Front



Address Verification



Side



Side



Street

Comparable Photos

Clear Val Plus



10103 Beach St Bellflower, CA 90706



Front

2 16222 Oregon Ave Bellflower, CA 90706



Front





Front

10308 Park St Bellflower, CA 90706 40131 Loan Number \$590,000

mber • As-Is Value

Scope of Work



REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Fabricio A. Alfaro, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Effective: 02/12/2020

Bellflower, CA 90706

40131 Loan Number

\$590,000 As-Is Value

Clear Val Plus by ClearCapital

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

by ClearCapital

10308 Park St

40131

\$590,000

• As-Is Value

Bellflower, CA 90706 Loan Number

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Fabricio A. Alfaro and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE	NAME	EFFECTIVE DATE	DATE OF REPORT
	Tamra Miller	02/12/2020	02/12/2020
LICENSE #	STATE	EXPIRATION	COMPANY
AR033837	CA	04/27/2020	Clario Appraisal Network

Effective: 02/12/2020

\$0

Property Condition Inspection





PROPERTY TYPE CURRENT USE PROJECTED USE SFR SFR SFR **OCCUPANCY GATED COMMUNITY** ATTACHED TYPE Occupied Detached No **PARKING TYPE STORIES UNITS** Detached Garage; 2 1 1 spaces **EXTERIOR REPAIRS INTERIOR REPAIRS TOTAL REPAIRS**

N/A

Condition & Marketability			
CONDITION		Good	Based on the visual inspection, the property looks in good condition and there is no evidence of damage.
SIGNIFICANT REPAIRS NEEDED	~	No	No repairs needed.
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	There is no current zoning violations or potential zoning changes affecting subject property.
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	~	Yes	The subject's market consist primarily of SFR's of wood frame construction with stucco, wood and masonry exteriors of generally average quality in average to good condition.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	Generally, properties in the area are in average quality to good condition.
BOARDED OR VACANT PROPERTIES NEAR SUBJECT		No	There is no boarded or vacant properties near subject property.
SUBJECT NEAR POWERLINES		No	No power lines near subject property.
SUBJECT NEAR RAILROAD	~	No	No railroad near subject property.
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	No commercial property near subject property.

\$0

Property Condition Inspection - Cont.



Condition & Marketability - cont.			
SUBJECT IN FLIGHT PATH OF AIRPORT	~	No	No airport flight path near property.
ROAD QUALITY	~	Good	Generally, roads in the area are in average quality to good condition.
NEGATIVE EXTERNALITIES	~	No	There is a freeway in close proximity, but does not affect marketability.
POSITIVE EXTERNALITIES	~	Yes	1/2 from schools, shopping centers, and 1/4 from freeway access.



Repairs Needed

ГЕМ	COMMENTS	CC	OST
xterior Paint	-	\$0)
Siding/Trim Repair		\$0)
exterior Doors	-	\$0)
Vindows	-	\$0)
Garage /Garage Ooor	-	\$0)
Roof/Gutters	-	\$0)
oundation	-	\$0)
encing	-	\$0)
andscape	-	\$0)
Pool /Spa	-	\$0)
)eck/Patio	-	\$0)
)riveway	-	\$0)
)ther	-	\$0)

Agent / Broker

ELECTRONIC SIGNATURE LICENSE # N

/Fabricio A. Alfaro/ 01265943 Fabricio A. Alfaro

NAME COMPANY

Sunrise Realty 02

02/12/2020

INSPECTION DATE

Appraisal Format: Appraisal Report

Client(s): Wedgewood Inc

Property ID: 28011724

Effective: 02/12/2020

Page: 15 of 15