
## by ClearCapital

#### 1387 18th St 40181 \$550,000 Los Osos, CA 93402 Loan Number As-Is Value



## **Subject Details**

PROPERTY TYPE	<b>GLA</b>
SFR	1,676 Sq. Ft.
BEDS	<b>BATHS</b>
3	2.0
<b>STYLE</b>	<b>YEAR BUILT</b>
Conventional	1978
LOT SIZE	<b>OWNERSHIP</b>
0.14 Acre(s)	Fee Simple
GARAGE TYPE	<b>GARAGE SIZE</b>
Attached Garage	2 Car(s)
HEATING	<b>COOLING</b>
Forced Air	None
<b>COUNTY</b>	<b>APN</b>
San Luis Obispo	038252026

## **Analysis Of Subject**

#### **CONDITION RATING**

						_						
1	2	3	4	5	6		1	2	3	4	5	6
	ance and	d physica	re some r al deterior							y rating m icable bui		
VIEW							LOCAT	ΓΙΟΝ				

Adverse

Residential

Beneficial

Neutral

Residential

**QUALITY RATING** 

Reside	IIIIdi	
Beneficial	Neutral	Adverse

SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior photos of the subject did not reveal an item of disrepair. Based upon an exterior-only inspection by the agent and p ... (continued in Appraiser Commentary Summary)

Provided by

Appraiser

**Sales Comparison** 

by ClearCapital

**1387 18th St** Los Osos, CA 93402 40181 Stoan Number

**\$550,000** • As-Is Value



				MOST COMPAR	ABLE		
	1387 18th St Los Osos, CA 93402	1536 17th St Los Osos, CA 93402		2 1373 13th St Los Osos, CA 93402	)	3 1645 14th St Los Osos, CA 93402	
COMPARABLE TYPE		Sale		Sale		Sale	
MILES TO SUBJECT		0.20 miles		0.31 miles		0.42 miles	
DATA/ VERIFICATION SOURCE	Public Records	MLS		MLS		MLS	
LIST PRICE				-		-	
LIST DATE	-	07/14/2019		08/26/2019		06/21/2019	
SALE PRICE/PPSF		\$550,000	\$354/Sq. Ft.	\$550,000	\$337/Sq. Ft.	\$615,000	\$358/Sq. Ft.
CONTRACT/ PENDING DATE		09/26/2019		12/16/2019		10/23/2019	
SALE DATE	-	10/25/2019		02/11/2020		11/07/2019	
DAYS ON MARKET		103		169		139	
LOCATION	N; Res	N; Res		N; Res		N; Res	
LOT SIZE	0.14 Acre(s)	0.14 Acre(s)		0.14 Acre(s)		0.14 Acre(s)	
VIEW	N; Res	N; Res		N; Res		N; Res	
DESIGN (STYLE)	Conventional	Conventional		Conventional		Conventional	
QUALITY OF CONSTRUCTION	Q4	Q4		Q4		Q4	
ACTUAL AGE	42	43		38		46	
CONDITION	C4	C4		C4		C3	-\$25,000
SALE TYPE		Arms length		Arms length		Arms length	
ROOMS/BEDS/BATHS	5/3/2	5/3/2		5/3/2		5/3/2	
GROSS LIVING AREA	1,676 Sq. Ft.	1,555 Sq. Ft.	\$8,000	1,633 Sq. Ft.		1,718 Sq. Ft.	
BASEMENT	None	None		None		None	
HEATING	Forced Air	Forced Air		Forced Air		Forced Air	
COOLING	None	None		None		None	
GARAGE	2 GA	2 GA		2 GA		2 DW	\$3,000
OTHER							
OTHER							
NET ADJUSTMENTS		1.4	\$8,000	0.0	00% \$0	-3.5	8% - \$22,000
GROSS ADJUSTMENTS		1.4	\$8,000	0.0	00% \$0	4.5	5% \$28,000
ADJUSTED PRICE			\$558,000		\$550,000		\$593,000

**40181** \$550,000 Loan Number • As-Is Value



## Value Conclusion + Reconciliation

**\$550,000** AS-IS VALUE **0-90 Days** EXPOSURE TIME **EXTERIOR** INSPECTION PERFORMED BY A 3RD PARTY

## Sales Comparison Analysis

## DESCRIPTION OF COMPARABLE SEARCH CRITERIA

All selected comparables were based on the standard guideline and were verified through the Multiple Listing Services (MLS) as Arms-Length-Transactions. All Comps surveyed are from the same demand area and are located within the subject's boundary. All adjustments were made where appropriate. All Comps were given most weight due to their recent sale and are similar to subject in terms of GLA, condition and located in subject area.

## EXPLANATION OF ADJUSTMENTS

The adjustments were based on market reaction and derived by paired sales analysis. The methodology used to determine the specific amount of each adjustment is based on paired sales analysis within subject's market and market reaction to several of the comps in the neighborhood. The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Even if the condition rating is the same as subject, a condition adjustment may still be warranted due to slight upgrades or lack thereof, based on MLS photos and agent commentary. The amount of the condition adjustment was based upon match pairs with remaining comps, if needed. The dissimilarities that have a 0 indicated in the adjustment column means the appraiser has acknowledged the difference; however, the market does not support any adjustment. GLA adjustments were given to sales at \$65 per SF. Most weight is given to comp 2 for lowest net and gross adjustments and recent sell date.

## ADDITIONAL COMMENTS (OPTIONAL)

The contract/pending date have been provided when available. The subject and comparable information were populated from ClearProp and cross referenced with online data sources. Any discrepancies were noted and corrected based on the most reliable data found.

## **Reconciliation Summary**

The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Weight is given to adjusted sale comparable 2 supported by comps 1 & 3. MLS data is assumed to be more reliable. The comparables presented within this analysis appear to be reliable indicators of value for the subject property. Comparables are located within the subject's market and considered reasonable purchase alternatives for the subject. Suggested value appears reasonable based upon the comparables. The subject's final value estimate is considered reasonable and supported by comp selection.

Effective: 02/27/2020

structure and indicate a good utilization of the improvements. Based on current market conditions, the existing structure as an SFR is financially feasible and maximal productive use. The highest and best use, as if vacant, would be to construct a Single-Family Residence.

Appraisal Format: Appraisal Report

Client(s): Wedgewood Inc

Property ID: 28105299

Effective: 02/27/2020

## Page: 4 of 15

It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior photos of the subject did not reveal an item of disrepair. Based upon an exterior-only inspection by the agent and photos, the subject is rated in C4 condition. The agent cited no observable repairs needed and the interior is assumed to be in similar condition as the exterior. The subject backs to open space with Bay Blvd beyond. This does not appear to impact

Analysis of Prior Sales & Listings

Highest and Best Use Additional Comments

**Clear** Val Plus

by ClearCapital

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.

Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this

The subject is a legally permissible use based on its current zoning. Also, the lot size, shape and land-to-building ratio allow the present

appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

## Appraiser Commentary Summary

## Subject Comments (Site, Condition, Quality)

marketability and would not need adjustments. From Page 6 Neighborhood and Market

40181 Loan Number

\$550,000 As-Is Value



Provided by

Appraiser

From Page 5





Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?

Event

Date

Price

Data Source

No

LISTING STATUS
Not Listed in Past Year
DATA SOURCE(S)
Public Records
EFFECTIVE DATE
02/28/2020
SALES AND LISTING HISTORY ANALYSIS

Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

## Order Information

<b>BORROWER</b> Catamount Properties 2018 LLC	<b>LOAN NUMBER</b> 40181
<b>PROPERTY ID</b>	ORDER ID
28105299	6631211
ORDER TRACKING ID	TRACKING ID 1
Citi_ClearVal_02.26.20	Citi_ClearVal_02.26.20

# LegalOWNERZONING DESC.AGAPAY,BENEDICTO C &<br/>JOSEPHINE AResidentialZONING CLASSZONING COMPLIANCERSFLegalLEGAL DESC.TN EL MORO BL 49 LTS 21 & 22


Highest and Best Use Economic IS HIGHEST AND BEST USE THE PRESENT USE **PROJECT TYPE R.E. TAXES HOA FEES** Yes \$7,328 N/A N/A PHYSICALLY POSSIBLE? FINANCIALLY FEASIBLE? **FEMA FLOOD ZONE** 06079C1029H LEGALLY PERMISSABLE? **MOST PRODUCTIVE USE?** FEMA SPECIAL FLOOD ZONE AREA No

40181 Loan Number


\$550,000 As-Is Value

Provided by

Appraiser



by ClearCapital



0.26

by ClearCapital

 1387 18th St
 40181

 Los Osos, CA 93402
 Loan Number

**40181** \$550,000 n Number • As-Is Value

## **Subject Photos**



Front



Address Verification



Address Verification



Side



Side

Appraisal Format: Appraisal Report

Client(s): Wedgewood Inc

Street Effective: 02/27/2020


by ClearCapital

 40181
 \$550,000

 Loan Number

 • As-Is Value

## **Subject Photos**



Street

Appraisal Format: Appraisal Report

ClearVal Plus by ClearCapital

## **Comparable Photos**

1536 17th St Los Osos, CA 93402



Front





Front





Front Appraisal Format: Appraisal Report



40181 Loan Number \$550,000 • As-Is Value



## Scope of Work

#### **REPORT FORMAT:**

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

#### PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

#### SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by David Matthew Hamilton, a licensed real estate agent having completed the above referenced Property Inspection.

#### AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

#### THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

#### **INTENDED USE:**

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

#### **INTENDED USER:**

The intended user of this appraisal report is the lender/client.

#### DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

#### (Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS none



\$550,000

As-Is Value

**40181** \$550,000 Loan Number • As-Is Value

## Assumptions, Conditions, Certifications, & Signature

Provided by Appraiser

**EXTRAORDINARY ASSUMPTIONS** 

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS none

Effective: 02/27/2020

by ClearCapital

10.1 personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is gualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

**APPRAISER'S CERTIFICATION COMMENTS** none

SIGNATURE	NAME	EFFECTIVE DATE	DATE OF REPORT
Kershi Broog	Keisha Brookins	02/27/2020	02/27/2020
LICENSE #	STATE	EXPIRATION	COMPANY
AR033309	CA	03/09/2022	Sonlite Appraisal Service

I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by David Matthew Hamilton and did not make a personal inspection of the property that is the subject of this report.

Assumptions, Conditions, Certifications, & Signature (Cont.)

1387 18th St Los Osos, CA 93402 Loan Number

\$550,000 As-Is Value

40181



Effective: 02/27/2020

by ClearCapital



Provided by Onsite Inspector

## **Property Condition Inspection**



PROPERTY TYPE	CURRENT USE	PROJECTED USE
SFR	SFR	SFR
OCCUPANCY	GATED COMMUNITY	ATTACHED TYPE
Occupied	No	Detached
PARKING TYPE Attached Garage; 2	<b>STORIES</b>	UNITS
spaces	2	I

## Condition & Marketability

-	,			
(	CONDITION	~	Good	Subject is in good condition average for the neighborhood
	SIGNIFICANT REPAIRS NEEDED	~	No	No significant repairs noted
	CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	No zoning violations
	SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	~	Yes	Good conformity to other homes in the area
	AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	Good condition similar to the subject
I	BOARDED OR VACANT PROPERTIES NEAR SUBJECT	~	No	None observed
0	SUBJECT NEAR POWERLINES		Yes	Not on property but about a half a block from subject
0	SUBJECT NEAR RAILROAD	~	No	None
0	SUBJECT NEAR COMMERCIAL PROPERTY	~	No	Commercial approximately .5 mile away
	SUBJECT IN FLIGHT PATH OF AIRPORT	~	No	No fights observed
I	ROAD QUALITY		Poor	Dirt road with pot holes from rain and travel
I	NEGATIVE EXTERNALITIES		Yes	Dirt road to property
I	POSITIVE EXTERNALITIES	~	Yes	Faces open pasture good views

Appraisal Format: Appraisal Report

## **Repairs Needed**

Exterior Repai	rs	
ITEM	COMMENTS	COST
Exterior Paint		\$0
Siding/Trim Repair		\$0
Exterior Doors		\$0
Windows	-	\$0
Garage /Garage Door		\$0
Roof/Gutters		\$0
Foundation	-	\$0
Fencing		\$0
Landscape		\$0
Pool /Spa	-	\$0
Deck/Patio		\$0
Driveway		\$0
Other	-	\$0
	TOTAL EXTERIOR REPAI	irs <b>\$0</b>

## Clear Val Plus by ClearCapital

## Agent / Broker

ELECTRONIC SIGNATURE /David Matthew Hamilton/ LICENSE # 01798015 NAME David Matthew Hamilton **COMPANY** Farrell Smyth Inc. **INSPECTION DATE** 02/27/2020