

by ClearCapital

Clear Val Plus





Subject Details

PROPERTY TYPE GLA

SFR 2,984 Sq. Ft.

BEDS BATHS 3.0

STYLE YEAR BUILT Mediterranean 1992

LOT SIZE OWNERSHIP 0.13 Acre(s) Fee Simple

GARAGE TYPE GARAGE SIZE Attached Garage 3 Car(s)

HEATING COOLING Forced Air Central

COUNTY APN

Los Angeles 7217006108

Analysis Of Subject




CONDITION RATING



The property is well maintained and feature limited repairs due to normal wear and tear

QUALITY RATING




Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW



Beneficial Neutral Adverse

LOCATION



SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior photos of the subject did not reveal an item of disrepair. Based upon an exterior-only inspection by the agent and p ... (continued in Appraiser Commentary Summary)

40537




Sales Comparison

by ClearCapital

Clear Val Plus





1972 Discovery Way

Signal Hill, CA 90755 Loan Number

\$985,000

As-Is Value

Value Conclusion + Reconciliation

Provided by Appraiser

\$985,000 AS-IS VALUE

0-90 DaysEXPOSURE TIME

EXTERIORINSPECTION PERFORMED
BY A 3RD PARTY

40537

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

A thorough search of the market was conducted to find the most recent and similar sales to match the subject property. Due to the subject's uniqueness and location, there were no exact model matches available. Dated sales over 6 months were necessary to consider for full compatibility. Subject is located in a stable market, so time adjustments are not necessary in this market. All selected comparables were based on the standard guideline and were verified through the Multiple Listing Services (MLS) as Arms-Length-Transactions. All Comps surveyed are from the same demand area and are located within the subject's boundary. All adjustments were made where appropriate. All Comps were given most weight due to their recent sale and are similar to subject in terms of GLA, condition and located in subject area.

EXPLANATION OF ADJUSTMENTS

The adjustments were based on market reaction and derived by paired sales analysis. The methodology used to determine the specific amount of each adjustment is based on paired sales analysis within subject's market and market reaction to several of the comps in the neighborhood. The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Even if the condition rating is the same as subject, a condition adjustment may still be warranted due to slight upgrades or lack thereof, based on MLS photos and agent commentary. The amount of the condition adjustment was based upon match pairs with remaining comps, if needed. The dissimilarities that have a 0 indicated in the adjustment column means the appraiser has acknowledged the difference; however, the market does not support any adjustment. GLA adjustments were given to sales at \$50 per SF. Most weight is given to comp 1 for closest location to the subject.

ADDITIONAL COMMENTS (OPTIONAL)

The contract/pending date have been provided when available. The unknown box may be checked to indicate that this information could not found or was not available. The subject and comparable information were populated from ClearProp and cross referenced with online data sources. Any discrepancies were noted and corrected based on the most reliable data found.

Reconciliation Summary

The condition of each comparable was verified through review of MLS commentary and interior MLS photos, if available. Weight is given to adjusted sale comparable 1 supported by comps 2 & 3. MLS data is assumed to be more reliable. The comparables presented within this analysis appear to be reliable indicators of value for the subject property. Comparables are located within the subject's market and considered reasonable purchase alternatives for the subject. Suggested value appears reasonable based upon the comparables. The subject's final value estimate is considered reasonable and supported by comp selection.

40537 Loan Number \$985,000

• As-Is Value



Appraiser Commentary Summary



Provided by Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

It should be noted that this is a desk appraisal only with no visible or physical inspection to the property. Information given is relied on by MLS and public records. Review of the PCI Report and exterior photos of the subject did not reveal an item of disrepair. Based upon an exterior-only inspection by the agent and photos, the subject is rated in C3 condition. The agent cited no observable repairs needed and the interior is assumed to be in similar condition as the exterior.

Neighborhood and Market

From Page 7

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.

Analysis of Prior Sales & Listings

From Page 5

The subject last sold Feb 21, 2019 per Public Records for \$975,000. The terms and condition of the prior sale was not provided to this appraiser. Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

Highest and Best Use Additional Comments

The subject is a legally permissible use based on its current zoning. Also, the lot size, shape and land-to-building ratio allow the present structure and indicate a good utilization of the improvements. Based on current market conditions, the existing structure as an SFR is financially feasible and maximal productive use. The highest and best use, as if vacant, would be to construct a Single-Family Residence.

Subject Details

by ClearCapital

Clear Val Plus

Sales and Listing History				
PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?	Event	Date	Price	Data Source
Yes	Sold	Feb 21, 2019	\$975,000	MLS 300653251
LISTING STATUS	Withdrawn	Feb 18, 2019	\$999,998	MLS 43954695
Listed in Past Year	Contingent	Feb 1, 2019	\$999,998	MLS 43954695
DATA SOURCE(S) MLS	Active	Jan 30, 2019	\$999,998	MLS PW18270171
	Contingent	Jan 29, 2019	\$999,998	MLS PW18270171
03/24/2020	Active	Jan 10, 2019	\$999,998	MLS PW18270171
	Withdrawn	Jan 10, 2019	\$999,998	MLS 43954695
	Withdrawn	Dec 3, 2018	\$1,039,000	MLS 43954695
	Active	Nov 9, 2018	\$1,039,000	MLS 300653251
	Cancelled	Oct 22, 2018	\$1,069,000	MLS 300563172
	Withdrawn	Sep 12, 2018	\$1,069,000	MLS 43687923
	Withdrawn	Sep 10, 2018	\$1,069,000	MLS NP18110909
	Active	Sep 3, 2018	\$1,069,000	MLS NP18110909
	Withdrawn	Jul 31, 2018	\$1,069,000	MLS NP18110909
	Withdrawn	Jul 25, 2018	\$1,069,000	MLS 43687923
	Active	Jul 7, 2018	\$1,069,000	MLS NP18110909
	Active	Jun 8, 2018	\$1,099,999	MLS 43687923

SALES AND LISTING HISTORY ANALYSIS

The subject last sold Feb 21, 2019 per Public Records for \$975,000. The terms and condition of the prior sale was not provided to this appraiser. Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal. The prior sale or transfer history analyses of the subject have been accurately and adequately provided.

Active

May 11, 2018

\$1,149,000

MLS 300563172

40537

\$985,000 • As-Is Value

Clear Val Plus by Clear Capital

Subject Details - Cont.

Loan Number



Order Information

BORROWER LOAN NUMBER

40537

Catamount Properties 2018,

LLC

PROPERTY ID ORDER ID 28234995 6671049

ORDER TRACKING ID TRACKING ID 1

Citi_ClearVal_03.23.20 40537

Legal

OWNERZONING DESC.TRAN,HIENResidential

ZONING CLASS ZONING COMPLIANCE

SHSP5* Legal

LEGAL DESC.

TR=48512 LOT 68

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE? FINANCIALLY FEASIBLE?

LEGALLY PERMISSABLE? MOST PRODUCTIVE USE?

Economic

R.E. TAXES HOA FEES PROJECT TYPE

\$12,470 N/A N/A

FEMA FLOOD ZONE

06037C1970F

FEMA SPECIAL FLOOD ZONE AREA

No

Clear Val Plus by Clear Capital

Neighborhood + Comparables





Sales in Last 12M

12

Months Supply

3.3

Avg Days Until Sale


65

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.



Subject Photos



Front



Address Verification



Side



Back



Street

Comparable Photos



Provided by Appraiser





Front

2055 Freeman Ave Signal Hill, CA 90755



Front

3 2635 E Catalina Dr # 18 Signal Hill, CA 90755



Front



Scope of Work



REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Evan Prather, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Clear Val Plus

Assumptions, Conditions, Certifications, & Signature



Provided by Appraiser

EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

1972 Discovery Way

Signal Hill, CA 90755

40537

\$985,000

• As-Is Value

Loan Number

Assumptions, Conditions, Certifications, & Signature (Cont.)



Provided by Appraiser

I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Evan Prather and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE NAME EFFECTIVE DATE DATE OF REPORT

Keisha Brookins 03/24/2020 03/24/2020

LICENSE # STATE EXPIRATION COMPANY

AR033309 CA 03/09/2022 Sonlite Appraisal Service

\$0

Clear Val Plus

Property Condition Inspection





PROPERTY TYPE CURRENT USE PROJECTED USE SFR SFR SFR **OCCUPANCY GATED COMMUNITY** ATTACHED TYPE Occupied Detached No **PARKING TYPE STORIES UNITS** 3 2 Attached Garage; 3 spaces **EXTERIOR REPAIRS INTERIOR REPAIRS TOTAL REPAIRS**

N/A

Condition & Marketability			
CONDITION	~	Good	The subject appeared to be in overall good exterior condition showing no obvious signs of deferred maintenance.
SIGNIFICANT REPAIRS NEEDED	~	No	-
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	~	Yes	
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	-
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	~	No	-
SUBJECT NEAR POWERLINES	~	No	-
SUBJECT NEAR RAILROAD	~	No	-
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	-

\$0

40537 Loan Number **\$985,000**• As-Is Value



Property Condition Inspection - Cont.





40537

Repairs Needed

TEM	COMMENTS	cos	Т
exterior Paint	-	\$0	
Siding/Trim Repair	-	\$0	
Exterior Doors	-	\$0	
Vindows	-	\$0	
Garage /Garage Door	-	\$0	
Roof/Gutters	-	\$0	
oundation	-	\$0	
encing	-	\$0	
andscape	-	\$0	
Pool /Spa	-	\$0	
Deck/Patio	-	\$0	
Driveway	-	\$0	
Other	-	\$0	
		TOTAL EXTERIOR REPAIRS	\$0

40537 Loan Number

\$985,000• As-Is Value



Agent / Broker

ELECTRONIC SIGNATURE

/Evan Prather/

LICENSE # 01140134

NAME

Evan Prather

COMPANY

INSPECTION DATE

MARK 1 REAL ESTATE

03/24/2020