


## Subject Details

|                      |                    |
|----------------------|--------------------|
| <b>PROPERTY TYPE</b> | <b>GLA</b>         |
| SFR                  | 2,208 Sq. Ft.      |
| <b>BEDS</b>          | <b>BATHS</b>       |
| 3                    | 2.0                |
| <b>STYLE</b>         | <b>YEAR BUILT</b>  |
| Conventional         | 1941               |
| <b>LOT SIZE</b>      | <b>OWNERSHIP</b>   |
| 0.19 Acre(s)         | Fee Simple         |
| <b>GARAGE TYPE</b>   | <b>GARAGE SIZE</b> |
| Attached Garage      | 1 Car(s)           |
| <b>HEATING</b>       | <b>COOLING</b>     |
| None                 | Unknown            |
| <b>COUNTY</b>        | <b>APN</b>         |
| Contra Costa         | 4261630034         |

## Analysis Of Subject

Provided by Appraiser

### CONDITION RATING




The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

### VIEW

🏠 Residential



### QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

### LOCATION

🏠 Residential











### SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The subject appears to be a 1 level detached SFR with 1 car garage with a Q4 quality rating and C4 condition rating based upon available online data and third party inspection report. No negative external influences noted by aerial imagery.



# Sales Comparison

Provided by  
Appraiser

|                           |  <b>710 Bayview Ct</b><br>El Sobrante, CA 94803<br> |  <b>3077 Deseret Dr</b><br>Richmond, CA 94803<br> |  <b>5254 Sunset Dr</b><br>El Sobrante, CA 94803<br> |  <b>1334 Parkridge Dr</b><br>Richmond, CA 94803<br> |
|---------------------------|---|---|--|---|
| COMPARABLE TYPE           | --  | Sale  | Sale   | Sale  |
| MILES TO SUBJECT          | --  | 0.65 miles  | 0.63 miles   | 0.62 miles  |
| DATA/ VERIFICATION SOURCE | Public Records  | MLS; Tax Records  | MLS; Tax Records   | MLS; Tax Records  |
| LIST PRICE                | --  | --  | --   | --  |
| LIST DATE                 | --  | 08/13/2020  | 08/31/2020   | 02/21/2020  |
| SALE PRICE/PPSF           | --  | \$770,000<br>\$352/Sq. Ft.  | \$750,000<br>\$326/Sq. Ft.   | \$688,000<br>\$331/Sq. Ft.  |
| CONTRACT/ PENDING DATE    | --  | 08/21/2020  | 09/08/2020   | 02/28/2020  |
| SALE DATE                 | --  | 09/21/2020  | 10/27/2020   | 05/28/2020  |
| DAYS ON MARKET            | --  | 39  | 57   | 97  |
| LOCATION                  | N; Res  | N; Res  | N; Res   | N; Res  |
| LOT SIZE                  | 0.19 Acre(s)  | 0.14 Acre(s)  | 0.24 Acre(s)   | 0.21 Acre(s)  |
| VIEW                      | N; Res  | B; LtdSght<br>-\$40,000   | B; LtdSght<br>-\$40,000  | B; LtdSght<br>-\$40,000   |
| DESIGN (STYLE)            | Conventional  | Conventional  | Conventional   | Conventional  |
| QUALITY OF CONSTRUCTION   | Q4  | Q4  | Q4   | Q4  |
| ACTUAL AGE                | 80  | 65  | 44   | 43  |
| CONDITION                 | C4  | C3<br>-\$40,000   | C3<br>-\$40,000  | C4  |
| SALE TYPE                 |   | Arms length   | Arms length  | Arms length   |
| ROOMS/BEDS/BATHS          | 6/3/2   | 9/3/3<br>-\$10,000  | 7/4/2  | 8/3/2.1<br>-\$5,000   |
| GROSS LIVING AREA         | 2,208 Sq. Ft.   | 2,186 Sq. Ft.   | 2,300 Sq. Ft.  | 2,081 Sq. Ft.   |
| BASEMENT                  | None  | Partial; 50<br>-\$25,000  | Partial; 0<br>-\$15,000  | None  |
| HEATING                   | None  | Forced Air  | Forced Air   | Forced Air  |
| COOLING                   | Unknown   | Unknown   | Unknown  | Unknown   |
| GARAGE                    | 1 GA  | 2 GA<br>-\$5,000  | 2 GA<br>-\$5,000   | 2 GA<br>-\$5,000  |
| OTHER                     | None noted  | Sup Upgrades<br>-\$35,000   | None noted   | None noted  |
| OTHER                     | --  | --  | --   | --  |
| NET ADJUSTMENTS           |   | -20.13% -\$155,000  | -13.33% -\$100,000   | -7.27% -\$50,000  |
| GROSS ADJUSTMENTS         |   | 20.13% \$155,000  | 13.33% \$100,000   | 7.27% \$50,000  |
| ADJUSTED PRICE            |   | \$615,000   | \$650,000  | \$638,000   |

## Sales Comparison (Continued)

Provided by  
Appraiser

|                           |  | MOST COMPARABLE  |               |  |    |
|---------------------------|--|--|---------------|--|----|
|                           |  <p><b>710 Bayview Ct</b><br/>El Sobrante, CA 94803</p> |  <p><b>2002 Thompson Ln</b><br/>El Sobrante, CA 94803</p> |               |  |    |
| COMPARABLE TYPE           | --   | Sale   |               |  |    |
| MILES TO SUBJECT          | --   | 0.41 miles   |               |  |    |
| DATA/ VERIFICATION SOURCE | Public Records   | MLS; Tax Records   |               |  |    |
| LIST PRICE                | --   | --   |               |  |    |
| LIST DATE                 | --   | 09/20/2020   |               |  |    |
| SALE PRICE/PPSF           | --   | \$590,000  | \$297/Sq. Ft. |  |    |
| CONTRACT/ PENDING DATE    | --   | 09/30/2020   |               |  |    |
| SALE DATE                 | --   | 10/21/2020   |               |  |    |
| DAYS ON MARKET            | --   | 31   |               |  |    |
| LOCATION                  | N; Res   | N; Res   |               |  |    |
| LOT SIZE                  | 0.19 Acre(s)   | 0.17 Acre(s)   |               |  |    |
| VIEW                      | N; Res   | N; Res   |               |  |    |
| DESIGN (STYLE)            | Conventional   | Conventional   |               |  |    |
| QUALITY OF CONSTRUCTION   | Q4   | Q4   |               |  |    |
| ACTUAL AGE                | 80   | 72   |               |  |    |
| CONDITION                 | C4   | C4   |               |  |    |
| SALE TYPE                 |  | Arms length  |               |  |    |
| ROOMS/BEDS/BATHS          | 6/3/2  | 6/3/2  |               |  |    |
| GROSS LIVING AREA         | 2,208 Sq. Ft.  | 1,984 Sq. Ft.  | \$22,400      |  |    |
| BASEMENT                  | None   | None   |               |  |    |
| HEATING                   | None   | Forced Air   |               |  |    |
| COOLING                   | Unknown  | Window/Unit  |               |  |    |
| GARAGE                    | 1 GA   | 1 GA   |               |  |    |
| OTHER                     | None noted   | --   | --            |  | -- |
| OTHER                     | --   | --   | --            |  | -- |
| NET ADJUSTMENTS           |  | 3.80%  | \$22,400      |  |    |
| GROSS ADJUSTMENTS         |  | 3.80%  | \$22,400      |  |    |
| ADJUSTED PRICE            |  |  | \$612,400     |  |    |

## Value Conclusion + Reconciliation



Provided by  
Appraiser

**\$615,000**  
AS-IS VALUE

**1-90 Days**  
EXPOSURE TIME

**EXTERIOR**  
INSPECTION PERFORMED  
BY A 3RD PARTY

### Sales Comparison Analysis

#### DESCRIPTION OF COMPARABLE SEARCH CRITERIA

A one mile radius search of detached homes was used.

#### EXPLANATION OF ADJUSTMENTS

Comps were selected from the overall market area and would be adjusted for differences in GLA, bath count and condition/upgrades. All comps appear to have similar "usable" lot area as the subject. No age or bedroom count adjustments were made as no market derived amount could be determined by available data. #1 and 2 were adjusted downward for superior overall condition and/or upgrades-remodeling. #3 had the most similar condition/appeal as the subject. #1 and 2 were adjusted for basement area, #1 appears partially furnished and #2 appears to be unfinished with both having buyer appeal. #1-3 were reported to have superior appeal views vs the subject. #4 brackets the subject's 1 car garage and deemed to have similar condition/appeal as the subject.

#### ADDITIONAL COMMENTS (OPTIONAL)

n/a

### Reconciliation Summary

Most weight given to comp 4 as it required fewest overall adjustments.

## Appraiser Commentary Summary

 Provided by  
Appraiser

### Subject Comments (Site, Condition, Quality)

From Page 1

The subject appears to be a 1 level detached SFR with 1 car garage with a Q4 quality rating and C4 condition rating based upon available online data and third party inspection report. No negative external influences noted by aerial imagery.

### Neighborhood and Market

From Page 7

As of the effective date of report, the data available indicated values were stable, demand and supply were in balance and marketing times were under 3 months; the most recent HDI information provided to reviewer confirms these mostly stable value trends. REO activity is low and area is not REO driven.

### Analysis of Prior Sales & Listings


From Page 6

The subject has not transferred in the past 3 years and comps have not been listed in the past 1 year based on data available.

### Highest and Best Use Additional Comments

The subject use as a detached SFR was deemed highest and best use. The Appraiser determined the subject's Highest and Best Use, after giving consideration to what is: (1) legally permissible and probable (zoning allowances, etc); (2) physically possible; (3) economically and financially feasible; and (4) what is most profitable, yielding the highest net return on the land and improvement. Based on current market conditions, the existing structure as a single family residence is financially feasible and maximally productive. The highest and best use, as if vacant, would be to construct a single family residence.

## Subject Details



### Sales and Listing History

**PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?**

No

**Event**

**Date**

**Price**

**Data Source**

**LISTING STATUS**

Not Listed in Past Year

**DATA SOURCE(S)**

Public Records

**EFFECTIVE DATE**

01/09/2021

**SALES AND LISTING HISTORY ANALYSIS**

The subject has not transferred in the past 3 years and comps have not been listed in the past 1 year based on data available.

### Order Information

**BORROWER**

Redwood Holdings LLC

**LOAN NUMBER**

43006

**PROPERTY ID**

29311601

**ORDER ID**

7031249

**ORDER TRACKING ID**

0107CV

**TRACKING ID 1**

0107CV

### Legal

**OWNER**

NELSON A MARTINEZ

**ZONING DESC.**

Residential

**ZONING CLASS**

RS M

**ZONING COMPLIANCE**

Legal

**LEGAL DESC.**

EL SOBRANTE MANOR 130

### Highest and Best Use

**IS HIGHEST AND BEST USE THE PRESENT USE**

Yes

**PHYSICALLY POSSIBLE?**



**FINANCIALLY FEASIBLE?**



**LEGALLY PERMISSABLE?**



**MOST PRODUCTIVE USE?**



### Economic

**R.E. TAXES**

\$8,001

**HOA FEES**

N/A

**PROJECT TYPE**

N/A

**FEMA FLOOD ZONE**


06013C0231G

**FEMA SPECIAL FLOOD ZONE AREA**

No

# Neighborhood + Comparables

Provided by Appraiser



Sales in Last 12M

**12**


Months Supply

**3.0**

Avg Days Until Sale







**60**

Subject Neighborhood as defined by the Appraiser



**NEIGHBORHOOD & MARKET COMMENTS**

As of the effective date of report, the data available indicated values were stable, demand and supply were in balance and marketing times were under 3 months; the most recent HDI information provided to reviewer confirms these mostly stable value trends. REO activity is low and area is not REO driven.



## Subject Photos



Front



Address Verification



Side



Side



Street



## Comparable Photos


Provided by  
Appraiser

1 3077 Deseret Dr  
Richmond, CA 94803



Front

2 5254 Sunset Dr  
El Sobrante, CA 94803



Front

3 1334 Parkridge Dr  
Richmond, CA 94803



Front

### Comparable Photos

Provided by  
Appraiser

4 2002 Thompson Ln  
El Sobrante, CA 94803



Front

## Scope of Work



Provided by  
Appraiser

### REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

### PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and the opinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

### SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Boris Vasquez, a licensed real estate agent having completed the above referenced Property Inspection.

### AT A MINIMUM, THE APPRAISER HAS:

1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
2. consulted and considered supplemental market data from readily available data sources;
3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

### THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

### INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

### INTENDED USER:

The intended user of this appraisal report is the lender/client.

### DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

1. buyer and seller are typically motivated;
2. both parties are well informed or well advised, and acting in what they consider their own best interest;
3. a reasonable time is allowed for exposure in the open market;
4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

**(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))**

### SCOPE OF WORK COMMENTS

1. I have, at a minimum, developed and reported this appraisal in accordance with the scope of work requirements stated in this appraisal report.

## Assumptions, Conditions, Certifications, & Signature

 Provided by  
Appraiser

### EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

### STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

## Assumptions, Conditions, Certifications, & Signature (Cont.)



**I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:**

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Boris Vasquez and did not make a personal inspection of the property that is the subject of this report.
10. I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

**SIGNATURE**

**NAME**

Kevin Felgenhauer

**EFFECTIVE DATE**

01/08/2021

**DATE OF REPORT**

01/09/2021

**LICENSE #**

AR034060

**STATE**

CA

**EXPIRATION**

05/18/2022

**COMPANY**

At Home Appraisals

## Comments - Continued

 Provided by  
Appraiser

### SCOPE OF WORK COMMENTS

1. I have, at a minimum, developed and reported this appraisal in accordance with the scope of work requirements stated in this appraisal report.

### EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

3. Based on reviewing the exterior photos and aerial imagery (when available), the extraordinary assumption has been made that there are no adverse site conditions or external factors (easements, encroachments, environmental conditions, land uses, etc) for the subject property and the boundary lines of the property are as stated in public records. The appraiser has not reviewed a current survey of the land or the title.

### LIMITING CONDITIONS COMMENTS

2. I relied on the additional data sources for subject property characteristics and the physical inspection information and photos performed by a local real estate professional (as stated in section 9 of the reviewer certification) and did not make a personal inspection of the property that is the subject of this report. I relied on the provided exterior photos and aerial imagery (when available) to report the condition of the improvements in factual, specific terms, and I used the provided exterior photos to identify and report the physical deficiencies that could affect the liveability, soundness, or structural integrity of the property.

# Property Condition Inspection

Provided by  
Onsite Inspector



|  |                                |                                  |
|--|--------------------------------|----------------------------------|
| <b>PROPERTY TYPE</b><br>SFR                      | <b>CURRENT USE</b><br>SFR      | <b>PROJECTED USE</b><br>SFR      |
| <b>OCCUPANCY</b><br>Occupied                     | <b>GATED COMMUNITY</b><br>No   | <b>ATTACHED TYPE</b><br>Detached |
| <b>PARKING TYPE</b><br>Built-In Garage; 1 spaces | <b>STORIES</b><br>2            | <b>UNITS</b><br>1                |
| <b>EXTERIOR REPAIRS</b><br>\$0                   | <b>INTERIOR REPAIRS</b><br>N/A | <b>TOTAL REPAIRS</b><br>\$0      |

## Condition & Marketability

|   |         |  |
|---|---------|--|
| <b>CONDITION</b>  | ⚠️ Fair | Property looks in average condition for the age.                 |
| <b>SIGNIFICANT REPAIRS NEEDED</b>   | ✅ No    | -  |
| <b>CURRENT ZONING VIOLATIONS/<br/>POTENTIAL ZONING CHANGES</b>                  | ✅ No    | -  |
| <b>SUBJECT CONFORMITY TO NEIGHBORHOOD<br/>(QUALITY, AGE, STYLE, &amp; SIZE)</b> | ✅ Yes   | -  |
| <b>AVERAGE CONDITION OF NEIGHBORING PROPERTIES</b>                              | ⚠️ Fair | Properties in the neighborhood are all in similar fair condition |
| <b>BOARDED OR VACANT PROPERTIES NEAR SUBJECT</b>                                | ✅ No    | -  |
| <b>SUBJECT NEAR POWERLINES</b>  | ✅ No    | -  |
| <b>SUBJECT NEAR RAILROAD</b>  | ✅ No    | -  |
| <b>SUBJECT NEAR COMMERCIAL PROPERTY</b>   | ✅ No    | -  |
| <b>SUBJECT IN FLIGHT PATH OF AIRPORT</b>  | ✅ No    | -  |
| <b>ROAD QUALITY</b>   | ⚠️ Fair | Road are public maintained                                       |
| <b>NEGATIVE EXTERNALITIES</b>   | ✅ No    | -  |
| <b>POSITIVE EXTERNALITIES</b>   | ✅ Yes   | Property is appealing because of the large lot.                  |

## Repairs Needed

### Exterior Repairs

| ITEM                   | COMMENTS | COST |
|------------------------|----------|------|
| Exterior Paint         | -        | \$0  |
| Siding/Trim Repair     | -        | \$0  |
| Exterior Doors         | -        | \$0  |
| Windows                | -        | \$0  |
| Garage /Garage Door    | -        | \$0  |
| Roof/Gutters           | -        | \$0  |
| Foundation             | -        | \$0  |
| Fencing                | -        | \$0  |
| Landscape              | -        | \$0  |
| Pool /Spa              | -        | \$0  |
| Deck/Patio             | -        | \$0  |
| Driveway               | -        | \$0  |
| Other                  | -        | \$0  |
| TOTAL EXTERIOR REPAIRS |          | \$0  |



## Agent / Broker

| ELECTRONIC SIGNATURE | LICENSE # | NAME          | COMPANY         | INSPECTION DATE |
|----------------------|-----------|---------------|-----------------|-----------------|
| /Boris Vasquez/      | 02015972  | Boris Vasquez | Bullplace Homes | 01/08/2021      |