
Clear Val Plus



Subject Details

PROPERTY TYPE GLA

SFR 1,791 Sq. Ft.

BEDS BATHS 2.0

STYLE YEAR BUILT 1964 Ranch

LOT SIZE OWNERSHIP 0.16 Acre(s) Fee Simple

GARAGE TYPE GARAGE SIZE Attached Garage 2 Car(s)

HEATING COOLING Forced Air Central


COUNTY APN

Ventura 1340263065

Analysis Of Subject



CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW



Beneficial Neutral Adverse

LOCATION

Effective: 03/01/2021

QUALITY RATING



SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The subject is located in the city of Ventura. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. The subject is described as a SFR with 1,719sf, 6/4/2 room count on a 1,791sf site (mostly level) built in 1964 in average co ... (continued in Appraiser Commentary Summary)


Provided by

Appraiser





Sales Comparison



Sales Comparison (Continued)



Provided by Appraiser

		MOST COMPA	ARABLE			
	8691 Neath St Ventura, CA 93004					
COMPARABLE TYPE		Sale				
MILES TO SUBJECT		0.34 miles				
DATA/ VERIFICATION SOURCE	MLS	MLS				
LIST PRICE						
LIST DATE		09/17/2020				
SALE PRICE/PPSF		\$650,000	\$400/Sq. Ft.			
CONTRACT/ PENDING DATE		10/21/2020				
ALE DATE	-	11/02/2020				
DAYS ON MARKET		46				
OCATION	N; Res	N; Res				
OT SIZE	0.16 Acre(s)	0.18 Acre(s)				
/IEW	N; Res	N; Res				
DESIGN (STYLE)	Ranch	Ranch				
QUALITY OF CONSTRUCTION	Q4	Q3	-\$25,000			
ACTUAL AGE	57	51				
CONDITION	C4	C4				
SALE TYPE		Arms length				
ROOMS/BEDS/BATHS	6/4/2	6/4/2				
GROSS LIVING AREA	1,791 Sq. Ft.	1,624 Sq. Ft.	\$25,000			
BASEMENT	None	None				
HEATING	Forced Air	Forced Air				
COOLING	Central	None				
GARAGE	2 GA	2 GA				
OTHER					-	
OTHER						
NET ADJUSTMENTS			0.00% \$0			
GROSS ADJUSTMENTS			7.69% \$50,000			
ADJUSTED PRICE			\$650,000			

8691 Neath St Ventura, CA 93004

\$640,000 As-Is Value

Loan Number

43249

Value Conclusion + Reconciliation

Provided by Appraiser

\$640,000 AS-IS VALUE

by ClearCapital

1-120 Days **EXPOSURE TIME** **EXTERIOR** INSPECTION PERFORMED BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

All comps are from the subject's neighborhood and are recently closed. The appraiser chose the best comparables available. Comps 1 and 2 are less than 100sf different in GLA therefore, no adjustment is warranted and per online photos comps 1 and 3 appear to be similar in condition/quality. Comp 2 had recent improvements and is superior in condition and quality while comp 4 has some minor improvements and is slightly superior in quality. Most weight is given to comp 4 for its similarity, proximity, and timeliness.

EXPLANATION OF ADJUSTMENTS

Amenity differences have been adjusted properly and are deemed customary for the area. Net/gross adjustments are within the standard 15%/25% guidelines. No negative external factors were noted which would negatively impact marketability. Value appears to be adequately supported.

ADDITIONAL COMMENTS (OPTIONAL)

Reconciliation Summary

After reconciliation of the supplied comparables, a value estimate of \$640k +/-appears to be considered reasonable as of 3/01/21. Extra ordinary assumptions were made in terms of interior condition/finishes, room count, etc. The comparables sales are acceptable and appear to be competitive in age, GLA and appeal to the subject.



Appraiser Commentary Summary



Subject Comments (Site, Condition, Quality)

From Page 1

The subject is located in the city of Ventura. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. The subject is described as a SFR with 1,719sf, 6/4/2 room count on a 1,791sf site (mostly level) built in 1964 in average condition. The subject is noted to need repairs and exterior paint. Estimated cost to paint is \$5k.

Neighborhood and Market

From Page 7

Market research indicates the subject's market have remained stable in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.

Analysis of Prior Sales & Listings

From Page 6

See above for the subject's listing/sale history.

Highest and Best Use Additional Comments

The highest and best use is as a SFR.



Subject Details





Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?

No

Contingent

Event

Date **Price** **Data Source**

Active

Jan 25, 2021

Jan 18, 2021

\$603,000

\$603,000

MLS V1-3467 MLS V1-3467

LISTING STATUS

Listed in Past Year

DATA SOURCE(S)

MLS

EFFECTIVE DATE

03/01/2021

SALES AND LISTING HISTORY ANALYSIS

See above for the subject's listing/sale history.

Legal

OWNER

ZONING DESC.

WILLIAM J HART

Residential

ZONING CLASS

ZONING COMPLIANCE

R1-6

Legal

LEGAL DESC.

TRACT 133301 LOT 79, REF: 030MR 051

Order Information

BORROWER

PROPERTY ID

LOAN NUMBER

Redwood Holdings LLC

ORDER ID

43249

29680052

7134028

ORDER TRACKING ID

TRACKING ID 1

0226CV

0226CV

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE?

FINANCIALLY FEASIBLE?

LEGALLY PERMISSABLE?

MOST PRODUCTIVE USE?

Economic

R.E. TAXES

HOA FEES

PROJECT TYPE

\$706

N/A

N/A

FEMA FLOOD ZONE


FEMA SPECIAL FLOOD ZONE AREA

No

Neighborhood + Comparables








Sales in Last 12M 50

Months Supply 1.0

Avg Days Until Sale

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

Market research indicates the subject's market have remained stable in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.



Clear Val Plus

Subject Photos



Front



Address Verification



Address Verification



Side



Street



Other



by ClearCapital

Comparable Photos



Provided by Appraiser





Front

8639 Aberdare St Ventura, CA 93004



Front

9184 Neath St Ventura, CA 93004



Front

Comparable Photos







Front

Scope of Work



REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by John Holladay, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

by ClearCapital

8691 Neath St Ventura, CA 93004 43249 Loan Number \$640,000

• As-Is Value

Assumptions, Conditions, Certifications, & Signature (Cont.)



Provided by Appraiser

I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by John Holladay and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE	NAME	EFFECTIVE DATE	DATE OF REPORT
Dina Blieard	Gina Blizard	03/01/2021	03/01/2021

LICENSE # STATE EXPIRATION COMPANY

AR030212 CA 02/27/2023 Independent Contractor

Clear Val Plus







PROPERTY TYPE CURRENT USE PROJECTED USE SFR SFR SFR **OCCUPANCY GATED COMMUNITY** ATTACHED TYPE Detached Occupied No **PARKING TYPE STORIES UNITS** Attached Garage; 2 1 1

spaces

EXTERIOR REPAIRS INTERIOR REPAIRS TOTAL REPAIRS \$5,000 N/A \$5,000

ondition & Marketability			
CONDITION	~	Good	Subject appears average from the exterior visual inspection and conform to the neighborhood.
SIGNIFICANT REPAIRS NEEDED	A	Yes	Exterior paint needed
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	None noted
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	~	Yes	Subject property conforms with other homes of similar design, age and condition in the immediate neighborhood
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	Neighborhood appears average overall.
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	~	No	None noted
SUBJECT NEAR POWERLINES	✓	No	None noted
SUBJECT NEAR RAILROAD	~	No	None noted
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	None noted



Property Condition Inspection - Cont.



Condition & Marketability - cont.			
SUBJECT IN FLIGHT PATH OF AIRPORT	~	No	None noted
ROAD QUALITY	~	Good	Appears adequately maintained
NEGATIVE EXTERNALITIES	~	No	None noted
POSITIVE EXTERNALITIES	~	No	None noted



Repairs Needed

TEM	COMMENTS	COST
xterior Paint	Paint exterior walls	\$5,000
iding/Trim Repair	-	\$0
xterior Doors		\$0
Vindows		\$0
arage /Garage loor		\$0
doof/Gutters		\$0
oundation	-	\$0
encing		\$0
andscape		\$0
ool /Spa		\$0
eck/Patio		\$0
riveway		\$0
ther		\$0
	TOTAL EXTERIOR REPAIRS	\$5,000

Agent / Broker

ELECTRONIC SIGNATURE

/John Holladay/

LICENSE # 01397810

NAME

John Holladay

COMPANY

ReMax Gold Coast Realtors

INSPECTION DATE

02/26/2021