


Subject Details

PROPERTY TYPE	GLA
SFR	1,266 Sq. Ft.
BEDS	BATHS
3	1.0
STYLE	YEAR BUILT
Spanish	1941
LOT SIZE	OWNERSHIP
0.13 Acre(s)	Fee Simple
GARAGE TYPE	GARAGE SIZE
Detached Garage	2 Car(s)
HEATING	COOLING
Forced Air	None
COUNTY	APN
Santa Clara	43908022

Analysis Of Subject

Provided by Appraiser

CONDITION RATING




The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

VIEW

Residential



QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

LOCATION

Residential











SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The subject is located in the city of San Jose. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. The subject is described as a SFR with 1,266sf, 5/3/1 room count built in 1941 in average condition. Per online photos impro ... **(continued in Appraiser Commentary Summary)**

Sales Comparison

Provided by
Appraiser

	MOST COMPARABLE			
	 1144 Malone Rd San Jose, CA 95125 	 1084 Bennett Way San Jose, CA 95125 	 1207 Curtner Ave San Jose, CA 95125 	 883 Malone Rd San Jose, CA 95125  <p>Virtual Open House Sat. Sept. 26 See Description for Event Registration Link</p>
COMPARABLE TYPE	--	Sale	Sale	Sale
MILES TO SUBJECT	--	0.16 miles	0.26 miles	0.46 miles
DATA/ VERIFICATION SOURCE	MLS	MLS	MLS	MLS
LIST PRICE	--	--	--	--
LIST DATE	--	11/18/2020	08/06/2020	09/17/2020
SALE PRICE/PPSF	--	\$1,315,000 \$1,096/Sq. Ft.	\$1,285,000 \$998/Sq. Ft.	\$1,375,000 \$1,028/Sq. Ft.
CONTRACT/ PENDING DATE	--	12/29/2020	08/18/2020	09/29/2020
SALE DATE	--	01/28/2021	09/14/2020	11/06/2020
DAYS ON MARKET	--	71	39	50
LOCATION	N; Res	N; Res	N; Res	N; Res
LOT SIZE	0.13 Acre(s)	0.13 Acre(s)	0.17 Acre(s)	0.15 Acre(s)
VIEW	N; Res	N; Res	N; Res	N; Res
DESIGN (STYLE)	Spanish	Spanish	Conventional	Conventional
QUALITY OF CONSTRUCTION	Q4	Q3 -\$25,000	Q3 -\$25,000	Q3 -\$25,000
ACTUAL AGE	80	83	74	70
CONDITION	C4	C3 -\$10,000	C3 -\$10,000	C3 -\$10,000
SALE TYPE		Arms length	Arms length	Arms length
ROOMS/BEDS/BATHS	5/3/1	4/2/1 \$10,000	5/3/2 -\$5,000	5/3/2 -\$5,000
GROSS LIVING AREA	1,266 Sq. Ft.	1,200 Sq. Ft.	1,288 Sq. Ft.	1,338 Sq. Ft.
BASEMENT	None	None	None	None
HEATING	Forced Air	Central	Forced Air	Central
COOLING	None	Unknown	Unknown	Unknown
GARAGE	2 GD	2 GD	2 GD	0 None \$10,000
OTHER	--	--	--	--
OTHER	--	--	--	--
NET ADJUSTMENTS		-1.90% -\$25,000	-3.11% -\$40,000	-2.18% -\$30,000
GROSS ADJUSTMENTS		3.42% \$45,000	3.11% \$40,000	3.64% \$50,000
ADJUSTED PRICE		\$1,290,000	\$1,245,000	\$1,345,000

Sales Comparison (Continued)

Provided by
Appraiser

	 1144 Malone Rd San Jose, CA 95125 	 2154 Parkwood Way San Jose, CA 95125 			
COMPARABLE TYPE	--	Sale			
MILES TO SUBJECT	--	0.72 miles			
DATA/ VERIFICATION SOURCE	MLS	MLS			
LIST PRICE	--	--			
LIST DATE	--	03/03/2020			
SALE PRICE/PPSF	--	\$1,350,000	\$1,173/Sq. Ft.		
CONTRACT/ PENDING DATE	--	03/12/2020			
SALE DATE	--	04/01/2020			
DAYS ON MARKET	--	29			
LOCATION	N; Res	N; Res			
LOT SIZE	0.13 Acre(s)	0.15 Acre(s)			
VIEW	N; Res	N; Res			
DESIGN (STYLE)	Spanish	Ranch			
QUALITY OF CONSTRUCTION	Q4	Q4			
ACTUAL AGE	80	69			
CONDITION	C4	C4			
SALE TYPE		Arms length			
ROOMS/BEDS/BATHS	5/3/1	5/3/1			
GROSS LIVING AREA	1,266 Sq. Ft.	1,151 Sq. Ft.	\$57,000		
BASEMENT	None	None			
HEATING	Forced Air	Central			
COOLING	None	Ventilation			
GARAGE	2 GD	2 GD			
OTHER	--	--	--	--	--
OTHER	--	--	--	--	--
NET ADJUSTMENTS			4.22%	\$57,000	
GROSS ADJUSTMENTS			4.22%	\$57,000	
ADJUSTED PRICE				\$1,407,000	

Value Conclusion + Reconciliation



Provided by
Appraiser

\$1,290,000
AS-IS VALUE

1-120 Days
EXPOSURE TIME

EXTERIOR
INSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

All comps are from the subject's neighborhood and are recently closed. The appraiser chose the best comparables available. Comps 1- 3 are less than 100sf different in GLA therefore, no adjustment is warranted. Per online photos comps 1- 3 had recent improvements and appear to be super in condition and quality to the subject. Comp 1 appears to be similar in condition and quality to the subject. Most weight is given to comp 1 for its proximity and timeliness.

EXPLANATION OF ADJUSTMENTS


Amenity differences have been adjusted properly and are deemed customary for the area. Net/gross adjustments are within the standard 15%/25% guidelines. No negative external factors were noted which would negatively impact marketability. Value appears to be adequately supported.

ADDITIONAL COMMENTS (OPTIONAL)

Reconciliation Summary

After reconciliation of the supplied comparables, a value estimate of \$1,290,000 +/- appears to be considered reasonable as of 2/10/21. Extra ordinary assumptions were made in terms of interior condition/finishes, room count, etc. The comparables sales are acceptable and appear to be competitive in age, GLA and appeal to the subject.

Appraiser Commentary Summary

 Provided by
Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

The subject is located in the city of San Jose. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. The subject is described as a SFR with 1,266sf, 5/3/1 room count built in 1941 in average condition. Per online photos improvements include: wood and tile flooring, tile countertops, fireplace, detached office, and a 2 car garage.

Neighborhood and Market

From Page 7

Market research indicates the subject's market have remained stable in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.

Analysis of Prior Sales & Listings

From Page 6

See above for the subject's listing/sale history.

Highest and Best Use Additional Comments

The highest and best use is as a SFR.

Subject Details



Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?

No ● Pending Date Price Data Source
Jan 22, 2021 \$1,249,950 MLS 40917480

LISTING STATUS

Listed in Past Year ● Active Date Price Data Source
Aug 20, 2020 \$1,249,950 MLS 40917480

DATA SOURCE(S)

MLS

EFFECTIVE DATE

02/10/2021

SALES AND LISTING HISTORY ANALYSIS

See above for the subject's listing/sale history.

Order Information

BORROWER

Redwood Holdings LLC

LOAN NUMBER

43274

PROPERTY ID

29512631

ORDER ID

7092388

ORDER TRACKING ID

0207CV

TRACKING ID 1

0207CV

Legal

OWNER

CAMARILLO,ALFONSO G & MARIA GUADALUPE TRUST

ZONING DESC.

Residential

ZONING CLASS

R1-8

ZONING COMPLIANCE

Legal

LEGAL DESC.

unavailable

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE?



FINANCIALLY FEASIBLE?



LEGALLY PERMISSABLE?



MOST PRODUCTIVE USE?



Economic

R.E. TAXES

\$1,918

HOA FEES

N/A

PROJECT TYPE

N/A

FEMA FLOOD ZONE


X

FEMA SPECIAL FLOOD ZONE AREA

No

Neighborhood + Comparables

Provided by Appraiser



Sales in Last 12M

132

Months Supply


0.5

Avg Days Until Sale


14

Subject Neighborhood as defined by the Appraiser

TYPE



BUILT-UP




NEIGHBORHOOD & MARKET COMMENTS

Market research indicates the subject's market have remained stable in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.

DEMAND / SUPPLY




VALUES




PRICE




GROSS LIVING AREA



YEAR BUILT



SITE SIZE



Subject Photos



Front



Address Verification



Side



Side



Street



Dining Room

Comparable Photos

Provided by
Appraiser

1 1084 Bennett Way
San Jose, CA 95125



Front

2 1207 Curtner Ave
San Jose, CA 95125



Front

3 883 Malone Rd
San Jose, CA 95125



Front

Comparable Photos

Provided by
Appraiser

4 2154 Parkwood Way
San Jose, CA 95125



Front

Scope of Work



Provided by
Appraiser

REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and the opinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Sara Greenwood, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
2. consulted and considered supplemental market data from readily available data sources;
3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

1. buyer and seller are typically motivated;
2. both parties are well informed or well advised, and acting in what they consider their own best interest;
3. a reasonable time is allowed for exposure in the open market;
4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Sara Greenwood and did not make a personal inspection of the property that is the subject of this report.
10. I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE

NAME

EFFECTIVE DATE

DATE OF REPORT

Gina Blizard

Gina Blizard

02/10/2021

02/11/2021

LICENSE #

STATE

EXPIRATION

COMPANY

AR030212

CA

02/28/2021

Independent Contractor

Property Condition Inspection

Provided by
Onsite Inspector



PROPERTY TYPE	CURRENT USE	PROJECTED USE
SFR	SFR	SFR
OCCUPANCY	GATED COMMUNITY	ATTACHED TYPE
Occupied	No	Detached
PARKING TYPE	STORIES	UNITS
Detached Garage; 2 spaces	1	1
EXTERIOR REPAIRS	INTERIOR REPAIRS	TOTAL REPAIRS
\$0	N/A	\$0

Condition & Marketability

CONDITION	✓ Good	Property is in average to go condition. No damage
SIGNIFICANT REPAIRS NEEDED	✓ No	No repairs needed
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	✓ No	No zoning violations
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	✓ Yes	Property conforms to the neighboring properties in age, condition
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	✓ Good	Condition of the homes in the neighborhood are in average to good condition.
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	✓ No	No boarded up or vacant homes
SUBJECT NEAR POWERLINES	✓ No	Not near powerlines
SUBJECT NEAR RAILROAD	✓ No	No railroad tracks nearby
SUBJECT NEAR COMMERCIAL PROPERTY	✓ No	Not close in proximity to commercial properties
SUBJECT IN FLIGHT PATH OF AIRPORT	✓ No	No located in a flight path
ROAD QUALITY	✓ Good	Road quality is good condition
NEGATIVE EXTERNALITIES	⚠ Yes	Malone is a larger than normal road that is considered a main arterial road
POSITIVE EXTERNALITIES	✓ No	No positive externalities

Repairs Needed

Exterior Repairs

ITEM	COMMENTS	COST
Exterior Paint	-	\$0
Siding/Trim Repair	-	\$0
Exterior Doors	-	\$0
Windows	-	\$0
Garage /Garage Door	-	\$0
Roof/Gutters	-	\$0
Foundation	-	\$0
Fencing	-	\$0
Landscape	-	\$0
Pool /Spa	-	\$0
Deck/Patio	-	\$0
Driveway	-	\$0
Other	-	\$0
TOTAL EXTERIOR REPAIRS		\$0

Agent / Broker

ELECTRONIC SIGNATURE	LICENSE #	NAME	COMPANY	INSPECTION DATE
/Sara Greenwood/	01840004	Sara Greenwood	Sara Greenwood RE	02/09/2021