
by ClearCapital

Clear Val Plus



Subject Details

PROPERTY TYPE GLA

SFR 2,522 Sq. Ft.

BEDS BATHS 3.0

STYLE YEAR BUILT Conventional 1974

LOT SIZE OWNERSHIP 0.11 Acre(s) Fee Simple

GARAGE TYPE GARAGE SIZE Attached Garage 2 Car(s)

HEATING COOLING Central None

COUNTY **APN**

Los Angeles 4114006020

Analysis Of Subject




CONDITION RATING




The property is well maintained and feature limited repairs due to normal wear and tear

QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW



LOCATION



SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

It should be noted that this is a desk appraisal only with no visible or physical inspection of the property. Information given is relied on by MLS, if available, public records, and PCI Report completed by a third party. The review of the PCI Report and photos of the subject did not reveal any items of disrepair.

Based ... (continued in Appraiser Commentary Summary)

43302

\$1,490,000 • As-Is Value


Clear Val Plus

by ClearCapital

Sales Comparison







43302 Loan Number \$1,490,000

As-Is Value

Value Conclusion + Reconciliation

Provided by Appraiser

\$1,490,000 AS-IS VALUE

0-90 DaysEXPOSURE TIME

EXTERIORINSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

Every effort was made to bracket the subject's room count, but none were available. The sales selected were the best available. No adjustment was made to room count to avoid double adjustments. Room count differences are considered in overall GLA adjustments. MLS shows comp 1 to be in average condition lacking upgrades. MLS states the comp 2 fully upgraded and was given a larger condition adjustment. Comp 3 was selected to bracket the subjects GLA but was built to the 2011 City of Los Angeles Green Building Standards and considered a premium in the area. A thorough search of the market was conducted to find the most recent and similar sales to match the subject property. Due to the subject's uniqueness, there were no exact model matches available. Dated sales over 6 months were necessary to consider for full compatibility. Time adjustments do not appear to be necessary in this market. The appraiser attempted to obtain an adequate amount of information in the normal course of business regarding the subject and comparable properties. Some of the standardized responses require by the UAD, especially those in which the appraiser has NOT had the opportunity to verify personally or measure, could mistakenly imply greater precision and reliability in the data than is factually correct or typical in the normal course of business. Examples include condition and quality ratings as well as comparable sales and listing data. The appraiser makes no representations, guarantees or warranties, express or implied, regarding building materials, their fitness, quality, condition or remaining economic life. Subject & Comparable data was generally obtained from the third-party sources including but not limited to the broker inspection report, local MLS, County Assessor, realtors, online resources and additional public data sources. Consequently, this information should be considered an "estimate" unless otherwise noted by the appraiser. Adjustments for variance in GLA were extracted from the market (pair analysis) at approximately \$75 per SF (for GLA exceeding 100 SF variance, per market analysis). Differences for architectural design/style are not supported per market. All selected comparables were based on the standard guideline and were verified through the Multiple Listing Services (MLS) as Arms-Length-Transactions. All Comps surveyed are from the same demand area and are located within the subject's boundary. All adjustments were made where appropriate. All Comps were given most weight due to their sale and like similarity.

EXPLANATION OF ADJUSTMENTS

The adjustments were based on market reaction and derived by paired sales analysis. The methodology used to determine the specific amount of each adjustment is based on paired sales analysis within the subject's market and market reaction to several of the comps in the neighborhood. The condition of each comparable was verified through a review of MLS commentary and interior MLS photos, if available. Even if the condition rating is the same as the subject, a condition adjustment may still be warranted due to slight upgrades or lack thereof, based on MLS photos and agent commentary. The amount of the condition adjustment was based upon match pairs with remaining comps, if needed. The dissimilarities that have a 0 indicated in the adjustment column means the appraiser has acknowledged the difference; however, the market does not support any adjustment. GLA adjustments were given to sales at \$75 per SF.

ADDITIONAL COMMENTS (OPTIONAL)

The contract/pending date have been provided when available. The unknown box may be checked to indicate that this information could not found or was not available. The subject and comparable information were populated from ClearProp and cross-referenced with online data sources. Any discrepancies were noted and corrected based on the most reliable data found.

Reconciliation Summary

The condition of each comparable was verified through a review of MLS commentary and interior MLS photos, if available. Weight is given to adjusted sale comparable 2 supported by comps 1 & 3. MLS data is assumed to be more reliable. The comparables presented within this analysis appear to be reliable indicators of value for the subject property. Comparables are located within the subject €™s market and considered reasonable purchase alternatives for the subject. The suggested value appears reasonable based upon the comparables. The subject of the subject

7823 W 79th St

Playa Del Rey, CA 90293

43302Loan Number

\$1,490,000 • As-Is Value

Appraiser Commentary Summary



Subject Comments (Site, Condition, Quality)

From Page 1

It should be noted that this is a desk appraisal only with no visible or physical inspection of the property. Information given is relied on by MLS, if available, public records, and PCI Report completed by a third party. The review of the PCI Report and photos of the subject did not reveal any items of disrepair. Based upon inspection by the agent and photos, the subject is rated in C3 condition. The agent cited no observable repairs needed.

Neighborhood and Market

From Page 6

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.

Analysis of Prior Sales & Listings

From Page 5

The subject was listed for sale 11/2020 and has sent been set to contingent as of 02/03/2021. Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal.

Highest and Best Use Additional Comments

The subject is a legally permissible use based on its current zoning. Also, the lot size, shape and land-to-building ratio allow the present structure and indicate a good utilization of the improvements. Based on current market conditions, the existing structure as an SFR is financially feasible and maximal productive use. The highest and best use, as if vacant, would be to construct a Single-Family Residence.

Loan Number

\$1,490,000

43302 As-Is Value

Subject Details

by ClearCapital



Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS? Date **Price Event Data Source** No Contingent Feb 3, 2021 \$1,725,000 MLS 302971964 **LISTING STATUS** Active Dec 7, 2020 \$1,725,000 MLS 302971964 Listed in Past Year Dec 7, 2020 MLS SB20247097 Active \$1,699,999 DATA SOURCE(S) Active Nov 25, 2020 \$1,699,999 MLS 302971964

EFFECTIVE DATE

02/14/2021

MLS

SALES AND LISTING HISTORY ANALYSIS

The subject was listed for sale 11/2020 and has sent been set to contingent as of 02/03/2021. Public records did not reveal any other prior sales or transfers of the subject property for the three years prior to the effective date of this appraisal.

Order Information	
BORROWER Redwood Holdings LLC	LOAN NUMBER 43302
PROPERTY ID 29530001	ORDER ID 7096679
ORDER TRACKING ID 0209CV	TRACKING ID 1 0209CV

Legal	
OWNER REFAT Y ANTOUN	ZONING DESC. Residential
ZONING CLASS LAR1	ZONING COMPLIANCE Legal
LEGAL DESC. TRACT NO 9809 LOT 21	


Highest and Best Use	
IS HIGHEST AND BEST USE TH	HE PRESENT USE
PHYSICALLY POSSIBLE?	FINANCIALLY FEASIBLE?
LEGALLY PERMISSABLE?	MOST PRODUCTIVE USE? ✓

Economic		
R.E. TAXES \$6,699	HOA FEES N/A	PROJECT TYPE N/A
FEMA FLOOD ZOI 06037C1760F	NE	
FEMA SPECIAL F	LOOD ZONE AREA	

by ClearCapital

Neighborhood + Comparables





Sales in Last 12M 58

Months Supply 1.0

Avg Days Until Sale

94

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

Market conditions are based on a review of sales data, market trends, and marketing times in competitive properties and markets. The market for single-unit residence properties is in balance at this time. Conventional financing appears to be stable; no special loan discounts, buy-downs or special financing is evident at this time. Interest rates are still attractive. Home values are in a stabilizing trend.



Subject Photos



Front



Address Verification




Side



Side



Street



Street

43302 Loan Number \$1,490,000

As-Is Value

Comparable Photos

Provided by Appraiser



by ClearCapital



Front

7933 W 80th St Playa Del Rey, CA 90293



Front

3 8300 Saran Dr Playa Del Rey, CA 90293



Front

Loan Number

\$1,490,000

As-Is Value

Scope of Work



REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Rodrigo Ursulo, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Loan Number

\$1,490,000 • As-Is Value

Assumptions, Conditions, Certifications, & Signature



Provided by Appraiser

EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

Loan Number

43302

\$1,490,000 • As-Is Value

Assumptions, Conditions, Certifications, & Signature (Cont.)



Provided by Appraiser

I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Rodrigo Ursulo and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

SIGNATURE NAME **EFFECTIVE DATE DATE OF REPORT** Keisha Brookins 02/10/2021 02/15/2021 Keisha Bruskins LICENSE # **STATE EXPIRATION COMPANY** AR033309 CA 03/09/2022 Sonlite Appraisal Service

7823 W 79th St

Playa Del Rey, CA 90293

43302 Loan Number \$1,490,000 • As-Is Value

Provided by Appraiser

Comments - Continued

APPRAISER'S CERTIFICATION COMMENTS

CORONAVIRUS - COVID-19 NATIONAL EMERGENCY: The global outbreak of a "novel coronavirus" known as COVID-19 was officially declared a pandemic by the World Health Organization (WHO) on March 11, 2020. The Federal Government has declared a National Emergency and the Governor of California has declared a State of Emergency for the state of California, regarding the ongoing Coronavirus - COVID-19 outbreak. As of the Effective Date of this appraisal and the date of this appraisal report it is too soon to evaluate the impact, if any, that the Coronavirus - COVID-19 outbreak will have on the local and regional real estate markets in which the Subject Property is located. The appraiser is completing the market analysis, however regarding the COVID-19 outbreak on the local market, there is limited data to support any market conditions adjustment relative to this event currently. As a result, no adjustment is made to reflect any change in the market conditions for the subject property on the effective date of value. The reader is cautioned and reminded that the conclusions presented in this appraisal report apply only as of the effective date(s) indicated. The appraiser makes no representation as to the effect on the subject property of this event, or any event, subsequent to the effective date of the appraisal. The Client and the Intended Users are advised to monitor market conditions in the short, medium, and long-term periods following the Effective Date of this report. If broad market indicators show a significant change in market conditions in either the regional or local market, the Client and Intended Users are advised to order a new appraisal of the Subject Property.

by ClearCapital

43302

Property Condition Inspection





PROPERTY TYPE CURRENT USE PROJECTED USE SFR SFR SFR **OCCUPANCY GATED COMMUNITY ATTACHED TYPE** Occupied No Detached **PARKING TYPE STORIES UNITS** Attached Garage; 2 1 1 spaces **EXTERIOR REPAIRS INTERIOR REPAIRS TOTAL REPAIRS** \$0 N/A \$0

CONDITION	~	Good	Property appeared to be in good condition from the exterior.
SIGNIFICANT REPAIRS NEEDED	~	No	No repairs needed or damages to report at time of inspection.
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	No current or potential zoning violations noted at time of inspection.
SUBJECT CONFORMITY TO NEIGHBORHOOD QUALITY, AGE, STYLE, & SIZE)	*	Yes	Subject conforms to neighborhood and is in similar condition to surrounding properties.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	✓	Good	The average condition for the neighboring properties is noted as "Good"
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	✓	No	No boarded or vacant properties were noted at time of inspection.
SUBJECT NEAR POWERLINES	~	No	No near powerlines were noted or observed.
SUBJECT NEAR RAILROAD	~	No	Subject is not near any railroad tracks.
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	There is no nearby commercial properties that would affect subject's marketability.

43302 Loan Number **\$1,490,000**• As-Is Value

Property Condition Inspection - Cont.



Condition & Marketability - cont.		
SUBJECT IN FLIGHT PATH OF AIRPORT	✓ No	Subject is not near an airport or airport flight path.
ROAD QUALITY	✓ Good	Subject's nearby roads are in good condition and consistent with nearby streets located in and around this neighborhood.
NEGATIVE EXTERNALITIES	✓ No	There are no negative externalities that affect subject property.
POSITIVE EXTERNALITIES	✓ No	There are no positive externalities that affect subject property.

43302Loan Number

\$1,490,000 • As-Is Value

Repairs Needed

by ClearCapital

ГЕМ	COMMENTS	COST
xterior Paint	-	\$0
iding/Trim Repair	-	\$0
xterior Doors	-	\$0
/indows	-	\$0
arage /Garage oor	-	\$0
oof/Gutters	-	\$0
oundation	-	\$0
encing	-	\$0
andscape	-	\$0
ool /Spa	-	\$0
eck/Patio	-	\$0
riveway	-	\$0
ther	-	\$0

7823 W 79th St

Playa Del Rey, CA 90293

43302 Loan Number \$1,490,000 • As-Is Value

Agent / Broker

ELECTRONIC SIGNATURE

LICENSE #

NAME

COMPANY

INSPECTION DATE

/Rodrigo Ursulo/ 01971199 Rodrigo Ursulo Pollard Properties 02/10/2021