
Clear Val Plus



### **Subject Details**

**PROPERTY TYPE GLA** 

**SFR** 2,987 Sq. Ft.

**BEDS BATHS** 4.0

**STYLE YEAR BUILT** Conventional 1952

**LOT SIZE OWNERSHIP** 0.32 Acre(s) Fee Simple

**GARAGE TYPE GARAGE SIZE** Attached Garage 2 Car(s)

**HEATING COOLING** Forced Air None

COUNTY **APN** 

Contra Costa 2661010013

# **Analysis Of Subject**




### **CONDITION RATING**



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

### **QUALITY RATING**



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

### **VIEW**



### LOCATION

Effective: 05/25/2021



### SUBJECT COMMENTS (SITE, CONDITION, QUALITY)


The subject is located in the city of Orinda. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. The subject is described as a SFR in a typical subdivision neighborhood. No negative influence was noted. It has 2,987sf, 9/ ... (continued in Appraiser Commentary Summary)

## Orinda, CA 94563



## **Sales Comparison**

Clear Val Plus



Orinda, CA 94563

44501 Loan Number \$1,800,000 • As-Is Value

### Value Conclusion + Reconciliation

Provided by Appraiser

**\$1,800,000**AS-IS VALUE

**1-120 Days**EXPOSURE TIME

**EXTERIOR**INSPECTION PERFORMED
BY A 3RD PARTY

### Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

All comps are from the subject's neighborhood and are recently closed. The appraiser chose the best comparables available. An across the bathroom adjustment was given which was unavoidable. Comps 1 and 3 are on slightly larger sites while comp 2 is on a slightly smaller site. In addition per online photos comps 1 and 2 are superior in condition/quality. An additional GLA adjustment was given for comp 3 as the total was too larger for the GLA box Most weight is given to comp 3 for its similarity.

**EXPLANATION OF ADJUSTMENTS** 

Amenity differences have been adjusted properly and are deemed customary for the area. Net/gross adjustments are within the standard 15%/25% guidelines. No negative external factors were noted which would negatively impact marketability. Value appears to be adequately supported.

ADDITIONAL COMMENTS (OPTIONAL)

### Reconciliation Summary

After reconciliation of the supplied comparables, a value estimate of \$1,800,000 is considered reasonable as of 5/25/21. Extra ordinary assumptions were made in terms of interior condition/finishes, room count, etc. The comparables sales are acceptable and appear to be competitive in age, GLA and appeal to the subject.

Orinda, CA 94563

44501 Loan Number \$1,800,000 • As-Is Value

### **Appraiser Commentary Summary**



### Subject Comments (Site, Condition, Quality)

From Page 1

The subject is located in the city of Orinda. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. The subject is described as a SFR in a typical subdivision neighborhood. No negative influence was noted. It has 2,987sf, 9/4/4 room count built in 1952 in average condition. No interior photos were available.

### Neighborhood and Market

From Page 6

Market research indicates the subject's market have remained stable in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.

### Analysis of Prior Sales & Listings

From Page 5

The subject has not been listed or sold within the last 3 years.

### Highest and Best Use Additional Comments

The highest and best use is as a SFR.

by ClearCapital

Orinda, CA 94563

44501 Loan Number \$1,800,000 As-Is Value

## **Subject Details**



### Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS? **Event** Date **Price Data Source** 

No

**LISTING STATUS** 

Not Listed in Past Year

DATA SOURCE(S)

Public Records

**EFFECTIVE DATE** 

05/25/2021

SALES AND LISTING HISTORY ANALYSIS

The subject has not been listed or sold within the last 3 years.

Legal

**OWNER ZONING DESC.** LCB LIVING TRUST Residential

**ZONING CLASS ZONING COMPLIANCE** 

**HOA FEES** 

N/A

R4 Legal

LEGAL DESC.

Economic

R.E. TAXES

**FEMA FLOOD ZONE** 

\$21.210

SLEEPY HOLLOW #2 LOT 109

Order Information

**BORROWER LOAN NUMBER** 

Redwood Holdings LLC 44501

**PROPERTY ID ORDER ID** 30345635 7312722

**ORDER TRACKING ID TRACKING ID 1** 

0520CV 0520CV

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE? FINANCIALLY FEASIBLE?

**MOST PRODUCTIVE USE?** 

**LEGALLY PERMISSABLE?** 

FEMA SPECIAL FLOOD ZONE AREA

No

**PROJECT TYPE** 

N/A

## **Neighborhood + Comparables**








Sales in Last 12M 30

Months Supply 1.0

Avg Days Until Sale

25

Subject Neighborhood as defined by the Appraiser



#### **NEIGHBORHOOD & MARKET COMMENTS**

Market research indicates the subject's market have remained stable in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.









Front



Front



Front



Address Verification



Side







Side



Side



Side



Side



Side







Side



Side



Side



Street



Street





Street Street

Provided by

Appraiser



# **Comparable Photos**







Front

46 El Gavilan Rd Orinda, CA 94563



Front





Front

Orinda, CA 94563

44501 Loan Number \$1,800,000 • As-Is Value

## **Scope of Work**

by ClearCapital



#### **REPORT FORMAT:**

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

#### PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

#### SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Debbye Deister, a licensed real estate agent having completed the above referenced Property Inspection.

#### AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

### THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

### INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

#### INTENDED USER:

The intended user of this appraisal report is the lender/client.

### **DEFINITION OF MARKET VALUE**

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Orinda, CA 94563

44501 Loan Number \$1,800,000 • As-Is Value

## **Assumptions, Conditions, Certifications, & Signature**



#### **EXTRAORDINARY ASSUMPTIONS**

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

#### STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

Orinda, CA 94563

44501 Loan Number \$1,800,000 • As-Is Value

## Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Debbye Deister and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE	NAME	EFFECTIVE DATE	DATE OF REPORT
Ina Bliend	Gina Blizard	05/25/2021	05/25/2021

LICENSE # STATE EXPIRATION COMPANY

AR030212 CA 02/27/2023 Independent Contractor

# **Property Condition Inspection**





**PROPERTY TYPE CURRENT USE PROJECTED USE** SFR SFR SFR **OCCUPANCY GATED COMMUNITY** ATTACHED TYPE Occupied Detached No **PARKING TYPE STORIES UNITS** 1 1 Attached Garage; 2 spaces

Attached Garage; 2 1 1 1 spaces

EXTERIOR REPAIRS INTERIOR REPAIRS TOTAL REPAIRS

\$0 N/A \$0

Condition & Marketability			
CONDITION	~	Good	No adverse conditions were noted at the time of inspection based on exterior observations. Wood Shingle roof appears to be nearing end of life
SIGNIFICANT REPAIRS NEEDED	~	No	No repairs noted based from drive-by observations. Adjustments might be necessary in the property if there are aspects of functional obsolescence
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	~	No	No zoning violations or potential zoning issues noted at time of drive-by inspection.
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	<b>~</b>	Yes	Located within an area of similar properties, subject conforms.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	~	Good	Subject neighborhood consists of similar Ranch style properties with similar build dates, condition and lot sizes.
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	~	No	-
SUBJECT NEAR POWERLINES	~	No	-
SUBJECT NEAR RAILROAD	~	No	-
SUBJECT NEAR COMMERCIAL PROPERTY	~	No	-

**Ln 44501** Loan Number

\$1,800,000 • As-Is Value



# **Property Condition Inspection - Cont.**



Condition & Marketability - cont.			
SUBJECT IN FLIGHT PATH OF AIRPORT	<b>/</b>	No	-
ROAD QUALITY	<b>*</b>	Good	-
NEGATIVE EXTERNALITIES	<b>*</b>	No	-
POSITIVE EXTERNALITIES	<b>*</b>	Yes	Subject located within a community with a highly rated School District, City dedicated BART Station, and close proximity to hwy 24 freeway access.



# **Repairs Needed**

ГЕМ	COMMENTS	CC	OST
xterior Paint	-	\$0	)
Siding/Trim Repair		\$0	)
exterior Doors	-	\$0	)
Vindows	-	\$0	)
Garage /Garage Ooor	-	\$0	)
Roof/Gutters	-	\$0	)
oundation	-	\$0	)
encing	-	\$0	)
andscape	-	\$0	)
Pool /Spa	-	\$0	)
)eck/Patio	-	\$0	)
)riveway	-	\$0	)
)ther	-	\$0	)

**181 Lombardy Ln**Orinda, CA 94563

44501 Loan Number \$1,800,000 • As-Is Value

## **Agent / Broker**

**ELECTRONIC SIGNATURE** 

/Debbye Deister/

**LICENSE #** 01426142

NAME

Debbye Deister

**COMPANY** 

Stonehurst Real Estate Services 05.

**INSPECTION DATE** 

05/21/2021