


Subject Details

PROPERTY TYPE	GLA
SFR	1,616 Sq. Ft.
BEDS	BATHS
4	2.0
STYLE	YEAR BUILT
Traditional	1969
LOT SIZE	OWNERSHIP
0.13 Acre(s)	Fee Simple
GARAGE TYPE	GARAGE SIZE
Attached Garage	2 Car(s)
HEATING	COOLING
Forced Air	None
COUNTY	APN
Alameda	417 019000100

Analysis Of Subject

Provided by Appraiser

CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW

Residential



LOCATION

Busy Road











SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The subject is located in the city of Hayward. The area consists of well maintained homes in a typical subdivision density neighborhood. No negative external influence was noted. The subject is located on a neighborhood feeder street and is described as a SFR with 6/4/2 room count, 1,616sf on a .09 acre site, built in 1 ... **(continued in Appraiser Commentary Summary)**

Sales Comparison

Provided by
Appraiser

	MOST COMPARABLE			
	 3245 Kelly St Hayward, CA 94541 	 2932 Kelly St Hayward, CA 94541 	 22884 Valley View Dr Hayward, CA 94541 	 3332 Jamie Way Hayward, CA 94541 
COMPARABLE TYPE	--	Sale	Sale	Sale
MILES TO SUBJECT	--	0.22 miles	0.16 miles	0.26 miles
DATA/ VERIFICATION SOURCE	MLS	MLS	MLS	MLS
LIST PRICE	--	--	--	--
LIST DATE	--	11/14/2020	02/19/2021	03/16/2021
SALE PRICE/PPSF	--	\$925,000 \$568/Sq. Ft.	\$915,000 \$608/Sq. Ft.	\$975,000 \$542/Sq. Ft.
CONTRACT/ PENDING DATE	--	11/23/2020	03/03/2021	03/22/2021
SALE DATE	--	12/31/2020	03/30/2021	04/15/2021
DAYS ON MARKET	--	47	39	30
LOCATION	A; BsyRd	A; BsyRd	N; Res -\$10,000	N; Res -\$10,000
LOT SIZE	0.13 Acre(s)	0.23 Acre(s) -\$10,000	0.21 Acre(s) -\$10,000	0.11 Acre(s)
VIEW	N; Res	N; Res	B; Other: canyon -\$10,000	N; Res
DESIGN (STYLE)	Traditional	Traditional	Ranch	Ranch
QUALITY OF CONSTRUCTION	Q4	Q3 -\$25,000	Q4	Q3 -\$25,000
ACTUAL AGE	52	79	81	42
CONDITION	C4	C3 -\$25,000	C4	C3 -\$25,000
SALE TYPE		Arms length	Arms length	Arms length
ROOMS/BEDS/BATHS	6/4/2	6/4/2	5/3/2	7/4/2
GROSS LIVING AREA	1,616 Sq. Ft.	1,628 Sq. Ft.	1,505 Sq. Ft. \$28,000	1,800 Sq. Ft. -\$46,000
BASEMENT	None	None	Full; 0 -\$10,000	None
HEATING	Forced Air	Central	Central	Forced Air
COOLING	None	None	Unknown	Window/Unit
GARAGE	2 GA	4 None \$10,000	0 None \$10,000	2 GA
OTHER	--	--	--	--
OTHER	--	--	--	--
NET ADJUSTMENTS		-5.41% -\$50,000	-0.22% -\$2,000	-10.87% -\$106,000
GROSS ADJUSTMENTS		7.57% \$70,000	8.52% \$78,000	10.87% \$106,000
ADJUSTED PRICE		\$875,000	\$913,000	\$869,000

Sales Comparison (Continued)

Provided by
Appraiser

	 <p>3245 Kelly St Hayward, CA 94541</p>	 <p>22516 Northview Dr Hayward, CA 94541</p>			
COMPARABLE TYPE	--	Sale			
MILES TO SUBJECT	--	0.24 miles			
DATA/ VERIFICATION SOURCE	MLS	Public Records			
LIST PRICE	--	--			
LIST DATE	--	03/02/2021			
SALE PRICE/PPSF	--	\$800,000	\$623/Sq. Ft.		
CONTRACT/ PENDING DATE	--	Unknown			
SALE DATE	--	03/25/2021			
DAYS ON MARKET	--	5			
LOCATION	A; BsyRd	N; Res	-\$10,000		
LOT SIZE	0.13 Acre(s)	0.14 Acre(s)			
VIEW	N; Res	N; Res			
DESIGN (STYLE)	Traditional	Ranch			
QUALITY OF CONSTRUCTION	Q4	Q4			
ACTUAL AGE	52	58			
CONDITION	C4	C4			
SALE TYPE		Arms length			
ROOMS/BEDS/BATHS	6/4/2	6/4/2			
GROSS LIVING AREA	1,616 Sq. Ft.	1,284 Sq. Ft.	\$83,000		
BASEMENT	None	None			
HEATING	Forced Air	Unknown			
COOLING	None	Unknown			
GARAGE	2 GA	2 GA			
OTHER	--	--		--	--
OTHER	--	--		--	--
NET ADJUSTMENTS			9.13%	\$73,000	
GROSS ADJUSTMENTS			11.63%	\$93,000	
ADJUSTED PRICE				\$873,000	

Value Conclusion + Reconciliation



Provided by
Appraiser

\$875,000
AS-IS VALUE

1-120 Days
EXPOSURE TIME

EXTERIOR
INSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

All comps are from the subject's neighborhood and are recently closed. The appraiser chose the best comparables available. Comp 1 is less than 100sf different in GLA therefore, no adjustment is warranted. Comps 1 and 2 are on slightly larger sites and comp 2 offers a view of the canyon. Comp 1 is located on the subject's street while comps 2 - 4 are on less traveled roads. Per online photos comps 1 and 3 are superior in condition/quality. Most weight is given to comp 1, located on the subject's street.

EXPLANATION OF ADJUSTMENTS


Amenity differences have been adjusted properly and are deemed customary for the area. Net/gross adjustments are within the standard 15%/25% guidelines. No negative external factors were noted which would negatively impact marketability. Value appears to be adequately supported.

ADDITIONAL COMMENTS (OPTIONAL)

Reconciliation Summary

After reconciliation of the supplied comparables, a value estimate of \$875k is considered reasonable as of 7/26/21. Extra ordinary assumptions were made in terms of interior condition/finishes, room count, etc. The comparables sales are acceptable and appear to be competitive in age, GLA and appeal to the subject.

Appraiser Commentary Summary

 Provided by Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

The subject is located in the city of Hayward. The area consists of well maintained homes in a typical subdivision density neighborhood. No negative external influence was noted. The subject is located on a neighborhood feeder street and is described as a SFR with 6/4/2 room count, 1,616sf on a .09 acre site, built in 1969 in average condition. The subject is noted to need \$9,725 in exterior repairs which is reflected in the condition grid.

Neighborhood and Market

From Page 7

Market research indicates the subject's market have remained stable/increasing in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.

Analysis of Prior Sales & Listings

From Page 6

The subject has not been listed or sold within the last 3 years.

Highest and Best Use Additional Comments

The highest and best use is as a SFR.

Subject Details

 Provided by Appraiser

Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?	Event	Date	Price	Data Source
--	-------	------	-------	-------------

No

LISTING STATUS

Not Listed in Past Year

DATA SOURCE(S)

Public Records

EFFECTIVE DATE

07/26/2021

SALES AND LISTING HISTORY ANALYSIS

The subject has not been listed or sold within the last 3 years.

Order Information

BORROWER	LOAN NUMBER
Redwood Holdings LLC	45654
PROPERTY ID	ORDER ID
30674722	7442656
ORDER TRACKING ID	TRACKING ID 1
0719CV	0719CV

Legal

OWNER	ZONING DESC.
AVIATOR PROPERTIES LLC	Residential
ZONING CLASS	ZONING COMPLIANCE
Residential	Legal
LEGAL DESC.	
Unavailable	

Highest and Best Use


IS HIGHEST AND BEST USE THE PRESENT USE	
Yes	
PHYSICALLY POSSIBLE?	FINANCIALLY FEASIBLE?
✓	✓
LEGALLY PERMISSABLE?	MOST PRODUCTIVE USE?
✓	✓

Economic

R.E. TAXES	HOA FEES	PROJECT TYPE
\$9,341	N/A	N/A
FEMA FLOOD ZONE		
X		
FEMA SPECIAL FLOOD ZONE AREA		
No		

Neighborhood + Comparables

Provided by
Appraiser



Sales in Last 12M

82

Months Supply


1.0

Avg Days Until Sale


21

Subject Neighborhood as defined by the Appraiser

TYPE




BUILT-UP




NEIGHBORHOOD & MARKET COMMENTS

Market research indicates the subject's market have remained stable/increasing in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.


DEMAND / SUPPLY




VALUES




PRICE




GROSS LIVING AREA



YEAR BUILT



SITE SIZE



Subject Photos



Front



Address Verification



Side



Side



Side



Street

Subject Photos



Street



Street



Other



Other



Other



Other

Subject Photos



Other



Other



Other

Comparable Photos

Provided by
Appraiser

1 2932 Kelly St
Hayward, CA 94541



Front

2 22884 Valley View Dr
Hayward, CA 94541



Front

3 3332 Jamie Way
Hayward, CA 94541



Front

Comparable Photos

Provided by
Appraiser

4 22516 Northview Dr
Hayward, CA 94541



Front

Scope of Work



Provided by
Appraiser

REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and the opinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Leticia Charles, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
2. consulted and considered supplemental market data from readily available data sources;
3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

1. buyer and seller are typically motivated;
2. both parties are well informed or well advised, and acting in what they consider their own best interest;
3. a reasonable time is allowed for exposure in the open market;
4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Leticia Charles and did not make a personal inspection of the property that is the subject of this report.
10. I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE

NAME

EFFECTIVE DATE

DATE OF REPORT

Gina Blizard

Gina Blizard

07/26/2021

07/26/2021

LICENSE #

STATE

EXPIRATION

COMPANY

AR030212

CA

02/27/2023

Independent Contractor

Property Condition Inspection

Provided by
Onsite Inspector



PROPERTY TYPE	CURRENT USE	PROJECTED USE
SFR	SFR	SFR
OCCUPANCY	GATED COMMUNITY	ATTACHED TYPE
Unknown	No	Detached
PARKING TYPE	STORIES	UNITS
Attached Garage; 2 spaces	1	1
EXTERIOR REPAIRS	INTERIOR REPAIRS	TOTAL REPAIRS
\$9,725	N/A	\$9,725

Condition & Marketability

CONDITION	⚠️ Fair	This is a single story home that appears to be in average to fair exterior condition with a skyline view.
SIGNIFICANT REPAIRS NEEDED	⚠️ Yes	There is a damaged window, damaged downspout, gutter or roof over garage and over grown landscaping
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	✅ No	-
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	✅ Yes	The subject conforms to the neighborhood in quality, age, style and size.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	✅ Good	Neighboring properties appear to be in average to good condition
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	✅ No	-
SUBJECT NEAR POWERLINES	✅ No	-
SUBJECT NEAR RAILROAD	✅ No	-
SUBJECT NEAR COMMERCIAL PROPERTY	✅ No	-

Property Condition Inspection - Cont.

 Provided by
Onsite Inspector

Condition & Marketability - cont.

SUBJECT IN FLIGHT PATH OF AIRPORT	✓	No	-
ROAD QUALITY	✓	Good	-
NEGATIVE EXTERNALITIES	✓	No	-
POSITIVE EXTERNALITIES	✓	No	-

Repairs Needed

Exterior Repairs

ITEM	COMMENTS	COST
Exterior Paint	exterior paint is distorted	\$7,800
Siding/Trim Repair	-	\$0
Exterior Doors	-	\$0
Windows	window at left side appears damaged	\$725
Garage /Garage Door	-	\$0
Roof/Gutters	roof over garage door appears damaged	\$800
Foundation	-	\$0
Fencing	-	\$0
Landscape	over grown	\$400
Pool /Spa	-	\$0
Deck/Patio	-	\$0
Driveway	-	\$0
Other	-	\$0
TOTAL EXTERIOR REPAIRS		\$9,725

Agent / Broker

ELECTRONIC SIGNATURE	LICENSE #	NAME	COMPANY	INSPECTION DATE
/Leticia Charles/	02044671	Leticia Charles	Realty One Group Future	07/20/2021