
Clear Val Plus



Subject Details

PROPERTY TYPE GLA

SFR 1,428 Sq. Ft.

BEDS BATHS3
2.0

STYLE YEAR BUILT
Conventional 1959

LOT SIZE OWNERSHIP
0.12 Acre(s) Fee Simple

GARAGE TYPEAttached Garage

2 Car(s)

HEATING COOLINGCentral Unknown


COUNTY APN

Los Angeles 5684029027

Analysis Of Subject


Provided by Appraiser

CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW



LOCATION

Effective: 08/31/2021



SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

The subject is located in the city of Los Angeles. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. No negative influence was noted. The subject is described as a SFR in a typical subdivision density neighborhood. It ha ... (continued in Appraiser Commentary Summary)


' ClearCapital



Sales Comparison

Clear Val Plus





Clear Val Plus

Sales Comparison (Continued)



| COMPARABLE TYPE | 2631 Range Rd Los Angeles, CA 90065 Aug 26 2021 08 09 38 PM | 2376 Las Colinas A Los Angeles, CA 90 | 041 | | | |
|---------------------------|--|--|---------------|--|---|--|
| MILES TO SUBJECT | _ | 0.21 miles | | | | |
| DATA/ VERIFICATION SOURCE | Public Records | MLS | | | | |
| LIST PRICE | _ | | | | | |
| | | | | | | |
| LIST DATE | - | 01/06/2021 | | | | |
| SALE PRICE/PPSF | | \$1,255,000 | \$917/Sq. Ft. | | | |
| CONTRACT/ PENDING DATE | | 03/31/2021 | | | | |
| SALE DATE | | 04/12/2021 | | | | |
| DAYS ON MARKET | | 96 | | | | |
| LOCATION | N; Res | N; Res | | | | |
| LOT SIZE | 0.12 Acre(s) | 0.22 Acre(s) | -\$20,000 | | | |
| VIEW | N; Res | N; Res | | | | |
| DESIGN (STYLE) | Conventional | Bungalow | | | | |
| QUALITY OF CONSTRUCTION | Q4 | Q4 | | | | |
| ACTUAL AGE | 62 | 99 | | | | |
| CONDITION | C4 | C4 | | | | |
| SALE TYPE | | Arms length | | | | |
| ROOMS/BEDS/BATHS | 7/3/2 | 6/2/1 | \$15,000 | | | |
| GROSS LIVING AREA | 1,428 Sq. Ft. | 1,368 Sq. Ft. | | | | |
| BASEMENT | None | None | | | | |
| HEATING | Central | Floor/Wall | | | | |
| COOLING | Unknown | None | | | | |
| GARAGE | 2 GA | 1 GD | \$5,000 | | | |
| OTHER | | - | | | - | |
| OTHER | | | | | - | |
| NET ADJUSTMENTS | | 0.0 | 00% \$0 | | | |
| GROSS ADJUSTMENTS | | 3. | 19% \$40,000 | | | |
| ADJUSTED PRICE | | | \$1,255,000 | | | |

46113 Loan Number \$1,370,000 • As-Is Value

Value Conclusion + Reconciliation

Provided by Appraiser

\$1,370,000 AS-IS VALUE **1-120 Days**EXPOSURE TIME

EXTERIOR
INSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

All comps are from the subject's neighborhood and are recently closed. The appraiser chose the best comparables available. Comps 2 and 4 are less than 100sf different in GLA therefore, no adjustment is warranted. Per online photos comps 1 and 3 are superior in condition/quality. Most weight is given to comp 2 for its similarity

EXPLANATION OF ADJUSTMENTS

Amenity differences have been adjusted properly and are deemed customary for the area. Net/gross adjustments are within the standard 15%/25% guidelines. No negative external factors were noted which would negatively impact marketability. Value appears to be adequately supported.

ADDITIONAL COMMENTS (OPTIONAL)

Reconciliation Summary

After reconciliation of the supplied comparables, a value estimate of \$1,370,000 is considered reasonable as of 8/31/21. Extra ordinary assumptions were made in terms of interior condition/finishes, room count, etc. The comparables sales are acceptable and appear to be competitive in age, GLA and appeal to the subject.

46113 Loan Number \$1,370,000 • As-Is Value

Appraiser Commentary Summary



Subject Comments (Site, Condition, Quality)

From Page 1

The subject is located in the city of Los Angeles. The area consists of well maintained homes 1 to 2 story and multi-family dwellings that for the most part have effective ages less than actual ages. No negative influence was noted. The subject is described as a SFR in a typical subdivision density neighborhood. It has 1,428sf, 7/3/2 room count built in 1959 in average condition. No interior photos were available.

Neighborhood and Market

From Page 7

Market research indicates the subject's market have remained stable/increasing in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.

Analysis of Prior Sales & Listings

From Page 6

See above for the subject's listing/sale history. Prior sale was an above market sale.

Highest and Best Use Additional Comments

The highest and best use is as a SFR.

Data Source



Subject Details



Appraiser

Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS? Event Date Price

Yes • Sold Mar 18, 2020 \$3,313,636 Public Records

LISTING STATUS

Not Listed in Past Year

DATA SOURCE(S)

Public Records

EFFECTIVE DATE

08/31/2021

SALES AND LISTING HISTORY ANALYSIS

See above for the subject's listing/sale history. Prior sale was an above market sale.

Order Information

BORROWER LOAN NUMBER

Redwood Holdings LLC 46113

PROPERTY ID ORDER ID 30915022 7534841

ORDER TRACKING ID TRACKING ID 1

0825CV 0825CV

Legal

OWNER ZONING DESC.

GOLDENROD DEV CORP Residential

ZONING CLASS ZONING COMPLIANCE

LAR1 Legal

LEGAL DESC.

TRACT # 19650 LOT 25

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE? FINANCIALLY FEASIBLE?

LEGALLY PERMISSABLE? MOST PRODUCTIVE USE?

~

Economic

R.E. TAXES HOA FEES PROJECT TYPE

\$10.540 N/A N/A

FEMA FLOOD ZONE

Χ

FEMA SPECIAL FLOOD ZONE AREA

No


Provided by

Appraiser

Clear Val Plus

Neighborhood + Comparables






Sales in Last 12M

Months Supply

1.0


Avg Days Until Sale
40

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

Market research indicates the subject's market have remained stable/increasing in value. The subject's market does not appear to be a REO driven market. Marketing time is noted at 90 days or less for properly priced homes.



Subject Photos



Front




Address Verification



Side



Side



Street



Street

by ClearCapital

Comparable Photos







Front

4364 York Blvd Los Angeles, CA 90041



Front

3 4325 Zaca Pl Los Angeles, CA 90065





Comparable Photos







Front

46113 Loan Number \$1,370,000 • As-Is Value

Scope of Work



REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and theopinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Rodrigo Ursulo, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

- 1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
- 2. consulted and considered supplemental market data from readily available data sources;
- 3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

- 1. buyer and seller are typically motivated;
- 2. both parties are well informed or well advised, and acting in what they consider their own best interest;
- 3. a reasonable time is allowed for exposure in the open market;
- 4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
- 5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

46113 Loan Number \$1,370,000 • As-Is Value

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

- 1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
- 2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
- 3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
- 4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
- 5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
- 6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
- 7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

46113 Loan Number \$1,370,000 • As-Is Value

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

- 1. The statements of fact contained in this report are true and correct.
- 2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
- 3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
- 4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
- 5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
- 6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
- 7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
- 8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
- 9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Rodrigo Ursulo and did not make a personal inspection of the property that is the subject of this report.
- 10.I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

| SIGNATURE | NAME | EFFECTIVE DATE | DATE OF REPORT |
|--------------|--------------|----------------|----------------|
| Dina Blieard | Gina Blizard | 08/31/2021 | 08/31/2021 |

LICENSE # STATE EXPIRATION COMPANY

AR030212 CA 02/27/2023 Independent Contractor

Property Condition Inspection





PROPERTY TYPE CURRENT USE PROJECTED USE
SFR SFR SFR

OCCUPANCY GATED COMMUNITY ATTACHED TYPE
Occupied No Detached

PARKING TYPE STORIES UNITS

PARKING TYPE STORIES UNITS
Attached Garage; 2 1 1 1 spaces

EXTERIOR REPAIRSSO
N/A
S0
TOTAL REPAIRS
\$0

| ondition & Marketability | | | |
|---|----------|------|--|
| CONDITION | * | Good | Subject address was verified by parcel location on subject street. Prope appeared to be in good condition from the exterior. |
| SIGNIFICANT REPAIRS NEEDED | ~ | No | No repairs needed or damages to report at time of inspection. |
| CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES | ~ | No | No current or potential zoning violations noted at time of inspection. |
| SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE) | ~ | Yes | Subject conforms to neighborhood and is in similar condition to surrounding properties. |
| AVERAGE CONDITION OF NEIGHBORING PROPERTIES | ~ | Good | The average condition for the neighboring properties is noted as "Good" |
| BOARDED OR VACANT PROPERTIES NEAR SUBJECT | ~ | No | No boarded or vacant properties were noted at time of inspection. |
| SUBJECT NEAR POWERLINES | ~ | No | No near powerlines were noted or observed. |
| SUBJECT NEAR RAILROAD | ~ | No | Subject is not near any railroad tracks. |
| SUBJECT NEAR COMMERCIAL PROPERTY | ~ | No | There is no nearby commercial properties that would affect subject's marketability. |



Property Condition Inspection - Cont.



| Condition & Marketability - cont. | | | |
|-----------------------------------|---|------|--|
| SUBJECT IN FLIGHT PATH OF AIRPORT | ~ | No | Subject is not near an airport or airport flight path. |
| ROAD QUALITY | ~ | Good | Subject's nearby roads are in good condition and consistent with nearby streets located in and around this neighborhood. |
| NEGATIVE EXTERNALITIES | ~ | No | There are no negative externalities that affect subject property. |
| POSITIVE EXTERNALITIES | ~ | No | There are no positive externalities that affect subject property. |



Repairs Needed

| ГЕМ | COMMENTS | CC | OST |
|------------------------|----------|-----|-----|
| xterior Paint | - | \$0 |) |
| Siding/Trim Repair | | \$0 |) |
| exterior Doors | - | \$0 |) |
| Vindows | - | \$0 |) |
| Garage /Garage Ooor | - | \$0 |) |
| Roof/Gutters | - | \$0 |) |
| oundation | - | \$0 |) |
| encing | - | \$0 |) |
| andscape | - | \$0 |) |
| Pool /Spa | - | \$0 |) |
|)eck/Patio | - | \$0 |) |
|)riveway | - | \$0 |) |
|)ther | - | \$0 |) |

46113 Loan Number \$1,370,000 • As-Is Value

Clear Val Plus by Clear Capital

Agent / Broker

ELECTRONIC SIGNATURE

/Rodrigo Ursulo/

LICENSE # 01971199

NAME

Rodrigo Ursulo

COMPANY

INSPECTION DATE

Pollard Properties 08/25/2021