


Subject Details

PROPERTY TYPE	GLA
SFR	1,822 Sq. Ft.
BEDS	BATHS
3	3.0
STYLE	YEAR BUILT
Historical	1974
LOT SIZE	OWNERSHIP
0.15 Acre(s)	Fee Simple
GARAGE TYPE	GARAGE SIZE
Built-In Garage	2 Car(s)
HEATING	COOLING
Central	Central
COUNTY	APN
Los Angeles	5684030024

Analysis Of Subject


Provided by Appraiser

CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.

QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW

🏠 Residential



LOCATION

🏠 Residential











SUBJECT COMMENTS (SITE, CONDITION, QUALITY)

the subject is assumed to be in considered in average condition. No interior inspection was performed.

Sales Comparison

Provided by
Appraiser

	MOST COMPARABLE			
	 4612 Yosemite Way Los Angeles, CA 90041 	 4978 Wawona St Los Angeles, CA 90041 	 4265 Yosemite Way Los Angeles, CA 90065 	 5040 Mosaic Ct Los Angeles, CA 90041 
COMPARABLE TYPE	--	Sale	Sale	Sale
MILES TO SUBJECT	--	0.30 miles	0.42 miles	0.43 miles
DATA/ VERIFICATION SOURCE	Public Records	Public Records	Public Records	MLS
LIST PRICE	--	--	--	--
LIST DATE	--	10/02/2020	10/01/2020	10/22/2020
SALE PRICE/PPSF	--	\$1,100,000 \$487/Sq. Ft.	\$960,000 \$545/Sq. Ft.	\$898,000 \$487/Sq. Ft.
CONTRACT/ PENDING DATE	--	11/06/2020	10/28/2020	10/22/2020
SALE DATE	--	10/21/2020 \$175,000	10/22/2020 \$175,000	10/22/2020 \$175,000
DAYS ON MARKET	--	31	27	0
LOCATION	N; Res	N; Res	N; Res	N; Res \$100,000
LOT SIZE	0.15 Acre(s)	0.26 Acre(s)	0.11 Acre(s)	0.03 Acre(s) \$25,000
VIEW	N; Res	N; Res	N; Res	N; Res
DESIGN (STYLE)	Historical	Conventional	Conventional	Mediterranean
QUALITY OF CONSTRUCTION	Q4	Q4	Q4	Q4
ACTUAL AGE	47	72	32	8 -\$50,000
CONDITION	C4	C4	C4	C4
SALE TYPE		Arms length	Arms length	Arms length
ROOMS/BEDS/BATHS	10/3/3	8/3/2	6/3/2	7/4/4
GROSS LIVING AREA	1,822 Sq. Ft.	2,260 Sq. Ft.	1,760 Sq. Ft.	1,845 Sq. Ft.
BASEMENT	None	None	None	None
HEATING	Central	Central	Central	Central
COOLING	Central	Central	Central	Central
GARAGE	2 GBI	2 GA	2 GA	2 GA
OTHER	--	--	--	--
OTHER	--	--	--	--
NET ADJUSTMENTS		15.91% \$175,000	18.23% \$175,000	27.84% \$250,000
GROSS ADJUSTMENTS		15.91% \$175,000	18.23% \$175,000	38.98% \$350,000
ADJUSTED PRICE		\$1,275,000	\$1,135,000	\$1,148,000

Sales Comparison (Continued)

Provided by
Appraiser

	 4612 Yosemite Way Los Angeles, CA 90041 	 4532 College View Ave Los Angeles, CA 90041 			
COMPARABLE TYPE	--	Listing			
MILES TO SUBJECT	--	0.42 miles			
DATA/ VERIFICATION SOURCE	Public Records	MLS			
LIST PRICE	--	\$1,499,000			
LIST DATE	--	09/14/2021			
SALE PRICE/PPSF	--	--	\$0/Sq. Ft.		
CONTRACT/ PENDING DATE	--	--			
SALE DATE	--				
DAYS ON MARKET	--	5			
LOCATION	N; Res	N; Res			
LOT SIZE	0.15 Acre(s)	0.25 Acre(s)			
VIEW	N; Res	N; Res			
DESIGN (STYLE)	Historical	Conventional			
QUALITY OF CONSTRUCTION	Q4	Q4			
ACTUAL AGE	47	71			
CONDITION	C4	C3	-\$125,000		
SALE TYPE		Arms length		Arms length	Arms length
ROOMS/BEDS/BATHS	10/3/3	6/3/2.1			
GROSS LIVING AREA	1,822 Sq. Ft.	1,659 Sq. Ft.			
BASEMENT	None	None			
HEATING	Central	Central			
COOLING	Central	Central			
GARAGE	2 GBI	2 GA			
OTHER	--	--		--	--
OTHER	--	--		--	--
NET ADJUSTMENTS			-8.34% -\$125,000		
GROSS ADJUSTMENTS			8.34% \$125,000		
ADJUSTED PRICE			\$1,374,000		

Value Conclusion + Reconciliation



\$1,275,000
AS-IS VALUE

0-45 Days
EXPOSURE TIME

EXTERIOR
INSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

The effort was made to bracket the subject in all major features and categories such as GLA, lot size, year built, location, and date of sale. Unfortunately, the most similar sales sold over 6 months ago. However, a time (date of sale) adjustment has been applied to the comparable sales based on the data put forth by the California association of realtors which is close to 20% increase in the last year and a half.

EXPLANATION OF ADJUSTMENTS

comp 3 has the most adjustments being on a much smaller lot and newer than the subject. The least weight has been applied to this comparable.


ADDITIONAL COMMENTS (OPTIONAL)

It was attempted to add an additional comparable. However, the website would not allow me to go back and add another one more recent. It should also be noted that there are sales similar in size to the subject have sold recently for 1.3 and 1.6M which are highly upgraded. So the potential of the subject appears to be significant in this neighborhood.

Reconciliation Summary

Based on the subject being in average condition, the subject's current market value is estimated to be \$1,275,000.

Appraiser Commentary Summary

 Provided by Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

the subject is assumed to be in considered in average condition. No interior inspection was performed.

Neighborhood and Market

From Page 8

The subject is located in the midst of a rather high demand area with interest rates remaining low and values have been steadily increasing for the past 10 years.

Analysis of Prior Sales & Listings

From Page 6

the subject has not been sold or listed in the past 3 years.

Highest and Best Use Additional Comments

subject's highest and best use is it's current use as it meets all four of the above criteria.

Subject Details

 Provided by Appraiser

Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS?

No

LISTING STATUS

Not Listed in Past Year

DATA SOURCE(S)

MLS,Public Records

EFFECTIVE DATE

09/19/2021

SALES AND LISTING HISTORY ANALYSIS

the subject has not been sold or listed in the past 3 years.

Subject Details - Cont.

 Provided by Appraiser

Order Information

BORROWER	LOAN NUMBER
Redwood Holdings LLC	46197
PROPERTY ID	ORDER ID
31040808	7580243
ORDER TRACKING ID	TRACKING ID 1
0913CV	0913CV

Legal

OWNER	ZONING DESC.
CRISANTA JOHNSON	Residential
ZONING CLASS	ZONING COMPLIANCE
LARE20	Legal

LEGAL DESC.

TRACT NO 341 LOT COM N 6 40' W 207.18 FT AND N 40 58' E 146.7 FT FROM MOST S COR OF LOT 19 TH N 40 58' E TO SW LINE OF LOT 76

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE

Yes

PHYSICALLY POSSIBLE?	FINANCIALLY FEASIBLE?
✓	✓
LEGALLY PERMISSABLE?	MOST PRODUCTIVE USE?
✓	✓

Economic

R.E. TAXES	HOA FEES	PROJECT TYPE
\$7,008	N/A	N/A

FEMA FLOOD ZONE


X

FEMA SPECIAL FLOOD ZONE AREA

No

Neighborhood + Comparables

Provided by Appraiser



Sales in Last 12M

36

Months Supply

1.3

Avg Days Until Sale

15

Subject Neighborhood as defined by the Appraiser

TYPE

Urban	Suburban	Rural
-------	-----------------	-------

BUILT-UP

>75%	25-75%	<25%
----------------	--------	------

NEIGHBORHOOD & MARKET COMMENTS





The subject is located in the midst of a rather high demand area with interest rates remaining low and values have been steadily increasing for the past 10 years.

DEMAND / SUPPLY

Shortage	Balance	Surplus
-----------------	---------	---------

VALUES

Declining	Stable	Increasing
-----------	--------	-------------------



Subject Photos



Front




Address Verification



Side



Side




Street



Street

Subject Photos



Other

Comparable Photos

Provided by
Appraiser

1 4978 Wawona St
Los Angeles, CA 90041



Front

2 4265 Yosemite Way
Los Angeles, CA 90065



Front

3 5040 Mosaic Ct
Los Angeles, CA 90041



Front

Comparable Photos

Provided by
Appraiser

4 4532 College View Ave
Los Angeles, CA 90041



Front

Scope of Work



Provided by
Appraiser

REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and the opinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by Rodrigo Ursulo, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
2. consulted and considered supplemental market data from readily available data sources;
3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

1. buyer and seller are typically motivated;
2. both parties are well informed or well advised, and acting in what they consider their own best interest;
3. a reasonable time is allowed for exposure in the open market;
4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by Rodrigo Ursulo and did not make a personal inspection of the property that is the subject of this report.
10. I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE

NAME

EFFECTIVE DATE

DATE OF REPORT

W.T. Bickers

WILLARD BICKERS

09/14/2021

09/19/2021

LICENSE #

STATE

EXPIRATION

COMPANY

AR028660

CA

01/31/2022

Willard Bickers

Property Condition Inspection

Provided by
Onsite Inspector



PROPERTY TYPE	CURRENT USE	PROJECTED USE
SFR	SFR	SFR
OCCUPANCY	GATED COMMUNITY	ATTACHED TYPE
Occupied	No	Detached
PARKING TYPE	STORIES	UNITS
Attached Garage; 2 spaces	1	1
EXTERIOR REPAIRS	INTERIOR REPAIRS	TOTAL REPAIRS
\$0	N/A	\$0

Condition & Marketability

CONDITION	✓ Good	Property appeared to be in good condition from the exterior.
SIGNIFICANT REPAIRS NEEDED	✓ No	No repairs needed or damages to report at time of inspection.
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	✓ No	No current or potential zoning violations noted at time of inspection.
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	✓ Yes	Subject conforms to neighborhood and is in similar condition to surrounding properties.
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	✓ Good	The average condition for the neighboring properties is noted as "Good"
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	✓ No	No boarded or vacant properties were noted at time of inspection.
SUBJECT NEAR POWERLINES	✓ No	No near powerlines were noted or observed.
SUBJECT NEAR RAILROAD	✓ No	Subject is not near any railroad tracks.
SUBJECT NEAR COMMERCIAL PROPERTY	✓ No	There is no nearby commercial properties that would affect subject's marketability.

Property Condition Inspection - Cont.

 Provided by
Onsite Inspector

Condition & Marketability - cont.

SUBJECT IN FLIGHT PATH OF AIRPORT	✓	No	Subject is not near an airport or airport flight path.
ROAD QUALITY	✓	Good	Subject's nearby roads are in good condition and consistent with nearby streets located in and around this neighborhood.
NEGATIVE EXTERNALITIES	✓	No	There are no negative externalities that affect subject property.
POSITIVE EXTERNALITIES	✓	No	There are no positive externalities that affect subject property.

Repairs Needed

Exterior Repairs

ITEM	COMMENTS	COST
Exterior Paint	-	\$0
Siding/Trim Repair	-	\$0
Exterior Doors	-	\$0
Windows	-	\$0
Garage /Garage Door	-	\$0
Roof/Gutters	-	\$0
Foundation	-	\$0
Fencing	-	\$0
Landscape	-	\$0
Pool /Spa	-	\$0
Deck/Patio	-	\$0
Driveway	-	\$0
Other	-	\$0
TOTAL EXTERIOR REPAIRS		\$0

Agent / Broker

ELECTRONIC SIGNATURE	LICENSE #	NAME	COMPANY	INSPECTION DATE
/Rodrigo Ursulo/	01971199	Rodrigo Ursulo	Pollard Properties	09/14/2021