

Subject Details

PROPERTY TYPE	GLA
SFR	1,233 Sq. Ft.
BEDS	BATHS
4	2.0
STYLE	YEAR BUILT
Ranch	1955
LOT SIZE	OWNERSHIP
6,579 Sq. Ft.	Fee Simple
GARAGE TYPE	GARAGE SIZE
Detached Garage	2 Car(s)
HEATING	COOLING
Forced Air	Unknown
COUNTY	APN
Ventura	2030164045

Analysis Of Subject

Provided by Appraiser

CONDITION RATING



The improvements feature some minor deferred maintenance and physical deterioration due to normal wear and tear.


QUALITY RATING



Dwellings with this quality rating meet or exceed the requirements of applicable building codes.

VIEW

Residential



LOCATION

Residential











SUBJECT COMMENTS (SITE, CONDITION, QUALITY)


As noted in the driveby inspection PCI report and additional Google search of the subject, it appears in C4 condition and not well maintained. If this is noted to be to the contrary to the actual condition, this could affect the value. The subject does have a 2 car detached garage with corner lot location. Site is flat and 100% usable

Sales Comparison

Provided by
Appraiser

	MOST COMPARABLE			
	 737 W Fir Ave Oxnard, CA 93033 	 640 W Cedar St Oxnard, CA 93033 	 2501 Jackson St Oxnard, CA 93033 	 1111 W Kamala St Oxnard, CA 93033 
COMPARABLE TYPE	--	Sale	Sale	Sale
MILES TO SUBJECT	--	0.11 miles	0.44 miles	0.36 miles
DATA/ VERIFICATION SOURCE	Public Records	MLS; Public Records	MLS; Public Records	MLS; Public Records
LIST PRICE	--	--	--	--
LIST DATE	--	09/02/2021	08/14/2021	04/28/2021
SALE PRICE/PPSF	--	\$580,000 \$559/Sq. Ft.	\$635,000 \$568/Sq. Ft.	\$570,000 \$417/Sq. Ft.
CONTRACT/ PENDING DATE	--	10/06/2021	09/01/2021	07/30/2021
SALE DATE	--	10/28/2021	10/06/2021	08/03/2021 \$30,000
DAYS ON MARKET	--	56	7	97
LOCATION	N; Res	N; Res	N; Res	N; Res
LOT SIZE	6,579 Sq. Ft.	6,400 Sq. Ft.	6,188 Sq. Ft.	6,150 Sq. Ft.
VIEW	N; Res	N; Res	N; Res	N; Res
DESIGN (STYLE)	Ranch	Ranch	Ranch	Ranch
QUALITY OF CONSTRUCTION	Q4	Q4	Q4	Q4
ACTUAL AGE	66	62	64	61
CONDITION	C4	C4	C3 -\$50,000	C4
SALE TYPE		Arms length	Arms length	Arms length
ROOMS/BEDS/BATHS	6/4/2	5/3/2 \$5,000	5/3/1 \$5,000	6/4/2
GROSS LIVING AREA	1,233 Sq. Ft.	1,038 Sq. Ft. \$16,575	1,118 Sq. Ft. \$9,775	1,368 Sq. Ft. -\$11,475
BASEMENT	None	None	None	None
HEATING	Forced Air	Forced Air	Forced Air	Forced Air
COOLING	Unknown	None	None	None
GARAGE	2 GD	2 GA	2 GD	2 GA
OTHER	no pool/spa	no pool/spa	no pool/spa	no pool/spa
OTHER	--	--	--	--
NET ADJUSTMENTS		3.72% \$21,575	-5.55% -\$35,225	3.25% \$18,525
GROSS ADJUSTMENTS		3.72% \$21,575	10.20% \$64,775	7.28% \$41,475
ADJUSTED PRICE		\$601,575	\$599,775	\$588,525

Value Conclusion + Reconciliation

 Provided by Appraiser

\$595,000
AS-IS VALUE

15-30 Days
EXPOSURE TIME

EXTERIOR
INSPECTION PERFORMED
BY A 3RD PARTY

Sales Comparison Analysis

DESCRIPTION OF COMPARABLE SEARCH CRITERIA

neighborhood boundaries, 1100-1600 sq.ft past 365 days, year built between 1950-1975

EXPLANATION OF ADJUSTMENTS

Paired sales derived the adjustments applied. Market conditions applied to Sale 3 as noted in paired sales to Comps 1 and 2.

ADDITIONAL COMMENTS (OPTIONAL)

Reconciliation Summary

Most weight placed on Sale 1 which is the most recent sale of a property in similar condition to the subject.

Appraiser Commentary Summary

 Provided by
Appraiser

Subject Comments (Site, Condition, Quality)

From Page 1

As noted in the driveby inspection PCI report and additional Google search of the subject, it appears in C4 condition and not well maintained. If this is noted to be to the contrary to the actual condition, this could affect the value. The subject does have a 2 car detached garage with corner lot location. Site is flat and 100% usable

Neighborhood and Market

From Page 6

The neighborhood is a community of average to good quality homes with a mixture of tract, custom, detached and attached homes. The neighborhood has public schools, neighborhood shopping, community parks, and good access to transportation Market supporting increasing sales prices over the past 3 months. Days on market decreasing and supply in demand.

Analysis of Prior Sales & Listings

From Page 5

Highest and Best Use Additional Comments

Highest and best use as Residential

Subject Details

 Provided by Appraiser

Sales and Listing History

PRIOR SALES OR TRANSFERS WITHIN 3 YEARS? **Event** **Date** **Price** **Data Source**
No

LISTING STATUS
Not Listed in Past Year

DATA SOURCE(S)
MLS,Public Records

EFFECTIVE DATE
11/29/2021

SALES AND LISTING HISTORY ANALYSIS

Order Information

BORROWER **LOAN NUMBER**
Redwood Holdings LLC 47115

PROPERTY ID **ORDER ID**
31699989 7772338

ORDER TRACKING ID **TRACKING ID 1**
1124CV 1124CV

Legal

OWNER **ZONING DESC.**
LETICIA G PINEDO Residential

ZONING CLASS **ZONING COMPLIANCE**
R1 Legal

LEGAL DESC.
LT 339 MP REF 022MR 036

Highest and Best Use

IS HIGHEST AND BEST USE THE PRESENT USE
Yes

PHYSICALLY POSSIBLE? **FINANCIALLY FEASIBLE?**
✓ ✓

LEGALLY PERMISSABLE? **MOST PRODUCTIVE USE?**
✓ ✓

Economic


R.E. TAXES **HOA FEES** **PROJECT TYPE**
\$918 N/A N/A

FEMA FLOOD ZONE
06111C0916E 1/20/2010

FEMA SPECIAL FLOOD ZONE AREA
No

Neighborhood + Comparables

Provided by Appraiser





Sales in Last 12M
58

Months Supply
1.3






Avg Days Until Sale
7

Subject Neighborhood as defined by the Appraiser



NEIGHBORHOOD & MARKET COMMENTS

The neighborhood is a community of average to good quality homes with a mixture of tract, custom, detached and attached homes. The neighborhood has public schools, neighborhood shopping, community parks, and good access to transportation Market supporting increasing sales prices over the past 3 months. Days on market decreasing and supply in demand.



Subject Photos



Front




Address Verification



Address Verification



Address Verification



Side



Side

Subject Photos



Street

Comparable Photos

Provided by
Appraiser

1 640 W Cedar St
Oxnard, CA 93033



Front

2 2501 Jackson St
Oxnard, CA 93033



Front

3 1111 W Kamala St
Oxnard, CA 93033



Front

Scope of Work



Provided by
Appraiser

REPORT FORMAT:

This report has been prepared under the following USPAP reporting option: Appraisal Report. The content of this Appraisal Report has been supplemented with additional information and data about the subject property and its market, as well as the data, reasoning, and analyses that were used in the valuation process. The cost approach and income approach have been omitted from this report as they are not necessary to produce credible assignment results. If the appraiser determines that credible assignment results cannot be provided without employing either the cost or income approaches to value, this assignment will be rejected by the appraiser or the scope expanded to the extent required to produce credible assignment results in compliance with USPAP. Unless otherwise stated, the appraiser has incorporated only the Sales Comparison Approach.

PURPOSE OF THE ASSIGNMENT:

The purpose of this Appraisal Report is to determine an and the opinion of the market value for the subject property, at which it could sell in a typical exposure time for the area, considering current market conditions, the condition of the subject and necessary repairs.

SCOPE OF WORK:

This Appraisal Report was performed by a Licensed or Certified Real Estate Appraiser to estimate the market value of the subject property being evaluated as of the effective date of value stated. Clear Capital has provided the appraiser with additional preliminary data resources for consideration in the analysis, which may include: Property Inspection, MLS records, and Public Records. Although the appraiser did not physically inspect the subject property, at a minimum the appraiser has considered the results of a recent visual property inspection completed by John Holladay, a licensed real estate agent having completed the above referenced Property Inspection.

AT A MINIMUM, THE APPRAISER HAS:

1. considered the additional data resources provided by Clear Capital as a resource for subject property and market data/characteristics;
2. consulted and considered supplemental market data from readily available data sources;
3. estimated the market value of the subject as of the effective date of this report restricting the desktop analysis to a sales comparison approach unless this was insufficient for credible assignment results.

THE APPRAISER HAS NOT:

1. Physically inspected the subject property or any of the comparables contained within the original report(s) or comparables presented in support of the appraiser's value opinion(s).

INTENDED USE:

The intended use of this Appraisal Report is for the lender/client to evaluate the property that is the subject of this appraisal for home equity line of credit, loan funding due diligence, loan sale, loan modification or loan securitization purposes.

INTENDED USER:

The intended user of this appraisal report is the lender/client.

DEFINITION OF MARKET VALUE

Market value means the most probable price which a property should bring in a competitive and open market under all conditions requisite to a fair sale, the buyer and seller each acting prudently and knowledgeably, and assuming the price is not affected by undue stimulus. Implicit in this definition is the consummation of a sale as of a specified date and the passing of title from seller to buyer under conditions whereby:

1. buyer and seller are typically motivated;
2. both parties are well informed or well advised, and acting in what they consider their own best interest;
3. a reasonable time is allowed for exposure in the open market;
4. payment is made in terms of cash in U.S. dollars or in terms of financial arrangements comparable thereto; and
5. the price represents the normal consideration for the property sold unaffected by special or creative financing or sales concessions granted by anyone associated with the sale.

(Source of Market Value Definition: Fannie Mae Selling Guide; Section B4-1.1-01: Definition of Market Value (04/15/2014))

SCOPE OF WORK COMMENTS

none

Assumptions, Conditions, Certifications, & Signature



EXTRAORDINARY ASSUMPTIONS

The appraiser did not perform a physical inspection, interior or exterior of the subject property or any of the comparable sales and assumes that the inspection information reported within the Property Inspection provided as well as the aerial images supplied and reviewed by the appraiser are accurate as of the effective date, unless otherwise stated. Should the information found in the Property Inspection be inaccurate, these assumptions could significantly alter the opinions and conclusions contained within this report.

EXTRAORDINARY ASSUMPTIONS AND HYPOTHETICAL CONDITIONS COMMENTS

none

STATEMENT OF ASSUMPTIONS AND LIMITED CONDITIONS:

1. The appraiser did not perform a physical inspection, interior or exterior, of the subject property or any of the comparable sales presented.
2. The physical inspection, interior or exterior, was performed by a licensed real estate professional as noted in the additional data resources provided. For the purposes of this analysis, the description of the subject and comps in the additional data resources provided for use in this analysis are assumed to be true, current and accurate unless specifically found to be otherwise.
3. The appraiser assumes no responsibility for matters of a legal nature affecting the property which is the subject of this assignment or the title thereto, nor does the appraiser render any opinion as to the title, which is assumed to be good and marketable and free from known value influencing easements, restrictions, encumbrances, leases, reservations, covenants, contracts, declarations, special assessments, ordinances or other items of a similar nature, unless otherwise noted.
4. The appraiser assumes that there are no hidden or unapparent conditions of the property, subsoil, or structures, which would render the property less valuable. The appraiser assumes no responsibility for such conditions, or for engineering which might be required to discover such factors.
5. Information, estimates, and opinions furnished to the appraiser, and contained in the additional data resources provided, were obtained from sources considered reliable and believed to be true and correct, unless stated elsewhere. If contradictory information is obtained and deemed more reliable, the appraiser will cite that source and the assumptions associated with that information.
6. Disclosure of the contents of the report is governed by USPAP and the Bylaws and Regulations of the professional appraisal organizations with which the appraiser is affiliated.
7. No change of any item in the report shall be made by anyone other than the appraiser and the appraiser shall have no responsibility for any such unauthorized change. The use of this report is limited to the named client and intended user(s) identified within this report.

LIMITING CONDITIONS COMMENTS

none

Assumptions, Conditions, Certifications, & Signature (Cont.)



I CERTIFY THAT, TO THE BEST OF MY KNOWLEDGE AND BELIEF:

1. The statements of fact contained in this report are true and correct.
2. The reported analyses, opinions, and conclusions are limited only by the reported assumptions and limiting conditions and are my personal, impartial, and unbiased professional analyses, opinions, and conclusions
3. I have no present or prospective interest in the property that is the subject of this report and no personal interest with respect to the parties involved.
4. Unless otherwise stated below in the "Additions to Appraiser's Certification" section; I have performed no services, as an appraiser or in any other capacity, regarding the property that is the subject of this report within the three-year period immediately preceding acceptance of this assignment.
5. I have no bias with respect to the property that is the subject of this report or to the parties involved with this assignment.
6. My engagement in this assignment was not contingent upon developing or reporting predetermined results.
7. My employment and/or compensation for completing this assignment is not contingent upon the development or reporting of a predetermined value or direction in value that favors the cause of the client, the amount of the value opinion, the attainment of a stipulated result, or the occurrence of a subsequent event directly related to the intended use of this appraisal.
8. My analyses, opinions, and conclusions were developed, and this report has been prepared, in conformity with the Uniform Standards of Professional Appraisal Practice.
9. The appraiser relied on the additional data sources for subject property characteristics and the physical inspection information performed by John Holladay and did not make a personal inspection of the property that is the subject of this report.
10. I personally prepared all conclusions and opinions about the real estate that were set forth in this appraisal report. If I relied on significant real property appraisal assistance from any individual or individuals in the performance of this appraisal or the preparation of this appraisal report, I have named such individual(s) and disclosed the specific tasks performed in this appraisal report. I certify that any individual so named is qualified to perform the tasks. I have not authorized anyone to make a change to any item in this appraisal report; therefore, any change made to this appraisal is unauthorized and I will take no responsibility for it.

APPRAISER'S CERTIFICATION COMMENTS

none

SIGNATURE

NAME

Michelle Rogers SRA

EFFECTIVE DATE

11/24/2021

DATE OF REPORT

11/30/2021

LICENSE #

AR014817

STATE

CA

EXPIRATION

05/27/2023

COMPANY

MBR Valuations

Property Condition Inspection

Provided by
Onsite Inspector



PROPERTY TYPE SFR	CURRENT USE SFR	PROJECTED USE SFR
OCCUPANCY Occupied	GATED COMMUNITY No	ATTACHED TYPE Detached
PARKING TYPE Attached Garage; 1 spaces	STORIES 1	UNITS 1
EXTERIOR REPAIRS \$0	INTERIOR REPAIRS N/A	TOTAL REPAIRS \$0

Condition & Marketability

CONDITION	✓ Good	Subject appears average from the exterior visual inspection and conforms to the neighborhood. Average size home with basic features and basic amenities. Lots of overgrown vegetation in front yard
SIGNIFICANT REPAIRS NEEDED	✓ No	NONE NOTED
CURRENT ZONING VIOLATIONS/ POTENTIAL ZONING CHANGES	✓ No	NONE NOTED
SUBJECT CONFORMITY TO NEIGHBORHOOD (QUALITY, AGE, STYLE, & SIZE)	✓ Yes	Subject property conforms with other homes of similar design, age and condition in the immediate neighborhood
AVERAGE CONDITION OF NEIGHBORING PROPERTIES	✓ Good	Neighborhood appears average overall. Average size homes with basic features and basic amenities.
BOARDED OR VACANT PROPERTIES NEAR SUBJECT	✓ No	NONE NOTED
SUBJECT NEAR POWERLINES	✓ No	NONE NOTED
SUBJECT NEAR RAILROAD	✓ No	NONE NOTED
SUBJECT NEAR COMMERCIAL PROPERTY	✓ No	NONE NOTED

Property Condition Inspection - Cont.

 Provided by
Onsite Inspector

Condition & Marketability - cont.

SUBJECT IN FLIGHT PATH OF AIRPORT	✓	No	NONE NOTED
ROAD QUALITY	✓	Good	APPEARS ADEQUATELY MAINTAINED
NEGATIVE EXTERNALITIES	✓	No	NONE NOTED
POSITIVE EXTERNALITIES	✓	No	NONE NOTED

Repairs Needed

Exterior Repairs

ITEM	COMMENTS	COST
Exterior Paint	-	\$0
Siding/Trim Repair	-	\$0
Exterior Doors	-	\$0
Windows	-	\$0
Garage /Garage Door	-	\$0
Roof/Gutters	-	\$0
Foundation	-	\$0
Fencing	-	\$0
Landscape	-	\$0
Pool /Spa	-	\$0
Deck/Patio	-	\$0
Driveway	-	\$0
Other	-	\$0
TOTAL EXTERIOR REPAIRS		\$0

Agent / Broker

ELECTRONIC SIGNATURE	LICENSE #	NAME	COMPANY	INSPECTION DATE
/John Holladay/	01397810	John Holladay	ReMax Gold Coast Realtors	11/24/2021